

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05647
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK.5
8. Well No.	1
9. Pool name or Wildcat	EUNICE MONUMENT G/SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER CONVERT TO INJECTION

2. Name of Operator
Amerada Hess Corporation

3. Address of Operator
P.O. DRAWER D, MONUMENT, NM 88265

4. Well Location
Unit Letter A : 660 Feet From The NORTH Line and 660 Feet From The EAST Line
Section 19 Township 19S Range 37E NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>CONVERT TO INJECTION WELL.</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #501 (07-23-96 THRU 08-07-96)

TYLER WELL SVC. & STAR TOOL MIRU. TOH W/PROD. EQUIPMENT. ND WELLHEAD, RELEASED TAC, INSTALLED ADAPTER FLANGE & NU BOP. TOH W/TBG., TAC, & SN. TIH W/RBP, SN & TBG. SET & GOT OFF RBP @ 3,784'. LOADED CSG. W/FW & BROKE CIRC. CIRC. WELL CLEAN OF OIL & GAS. RCV'D. 20 BBLs. OIL. CIRC. WELLBORE TO RMV. MIGRATING OIL. PRESS. TST'D. 5-1/2" CSG. TO 600# & CHARTED 30 MINS. CSG. HELD. SPOTTED 2 SKS. SAND TO COVER RBP @ 3,784'. TOH W/TBG., SN & RETRIEVING HEAD. LOADED 5-1/2" CSG. W/FW. ND BOP & UNSCREWED ADAPTER FLANGE. CHK'D. 5-1/2" & 7-5/8" X 5-1/2" INT. CSG. ANNULUS OUTLETS W/EXPLOSION MTR. INSTALLED NEW WELLHEAD. TST'D. WELLHEAD TO 3,000#. INSTALLED BOP. PRESS. TST'D. 5-1/2" CSG. TO 550# & CHARTED 30 MIN. TST. CSG. HELD. TIH W/RETRIEVING HEAD, SN & TBG. TAGGED SAND @ 3,767'. PU POWER SWIVEL. CIRC. SAND OFF FR. (CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 08-08-96

TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: Request Check to Bureau

JCBW

SP