

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
A-1543-1

7. Unit Agreement Name

8. Farm or Lease Name
Graham State (NCT-D)

9. Well No.
2

10. Field and Pool, or Wildcat
Eunice-Monument

12. County
Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL GAS WELL OTHER

1. Name of Operator
GULF OIL CORPORATION

2. Address of Operator
P. O. Box 670, Hobbs, NM 88240

3. Location of Well
UNIT LETTER P 660 FEET FROM THE South LINE AND 660 FEET FROM
THE East LINE, SECTION 19 TOWNSHIP 19-S RANGE 37-E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

11. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled production eqpt. Ppd 30 sx cmt, 3919' to 3813'; WOC. Ppd 30 sx cmt 3813' to 3608'. WOC. Spotted abandonment mud from 3608' to csg part @ 2159. Ppd 15 sx cmt, 100' plug on top of Yates formation 2578'-2478'.

Displaced hole with abandonment mud. Ppd 15 sx cmt, 100' plug 1600'-1500' on top of Salt Section. WOC. Stuck tbg @ 1365'. Press tbg & csg to 500# - held ok. Cut tbg @ 1360'. Ppd 5 sx cmt on top of tbg stub. Spotted abandonment mud 1327' to 50'. Set 10 sx cmt plug 50' to surface.

Install dry hole marker, cleaned & cleared location.

Work performed 2-22-79 to 2-26-79.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Glyn Stone TITLE Acting Area Engineer DATE 2-27-79

APPROVED BY Otto Wink TITLE OIL & GAS INSPECTOR DATE FEB 1 1980

CONDITIONS OF APPROVAL, IF ANY: