

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

F.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05654
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1589-1
7. Lease Name or Unit Agreement Name NORTH MONUMENT G/SA UNIT BLK. 6	
8. Well No.	5
9. Pool name or Wildcat	EUNICE MONUMENT G/SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTION WELL	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P.O. DRAWER D, MONUMENT, NM 88265	
4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>20</u> Township <u>19S</u> Range <u>37E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: CONVERT TO INJECTION WELL ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #605 (08-12-96 THRU 08-20-96)

TYLER WELL SVC. & STAR TOOL MIRU. UNSEATED PUMP. TOH W/PRODUCTION EQUIPMENT. INSTALLED BOP. TOH W/TBG., TAC, & SN. TIH W/RBP, SN & TBG. SET & GOT OFF BP @ 3,828'. CIRC. WELLBORE CLEAN. PRESS. TST'D. CSG. TO 600# & CHARTED 32 MIN. TST. CSG. HELD. RELEASED RBP & L.D. 1 JT. TBG. TOH W/TBG., SN & RBP. TIH W/BIT, BIT SUB, & TBG. TAGGED @ 3,988'. TOH W/TBG., BIT SUB & BIT. ROTARY WIRELINE MIRU. STRING SHOT O.H. W/400 GRAIN/FT. FR. 3,854'-3,988'. ROTARY WIRELINE RDMO. JARREL SVCS. MIRU. FOUND SBHP OF 250# @ 3,661'. FL @ 3,318'. JARREL SVCS. RDMO. TIH W/BIT, BIT SUB, SN & TBG. TAGGED @ 3,974'. PUMPED FW & BROKE CIRC. CLEAND OUT FILL FR. 3,974'-3,996'. RTNS. WERE FORMATION, SCALE & PERF. DEBRIS FR. STRING SHOT. TOH W/TBG., SN, BIT SUB & BIT. SCHLUMBERGER MIRU. LOGGED O.H. W/SONIC/CNL/GR TOOLS. PERF'D.
(CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 08/21/96
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

SEP 17 1996

TC BN

mp
CP