

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-05655 ✓
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1589-1
7. Lease Name or Unit Agreement Name NORTH MONUMENT G/SA UNIT BLK. 6
8. Well No. 6
9. Pool name or Wildcat EUNICE MONUMENT G/SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3675 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator AMERADA HESS CORPORATION
3. Address of Operator DRAWER D, MONUMENT, NEW MEXICO 88265	4. Well Location Unit Letter F : 1980 Feet From The NORTH Line and 1980 Feet From The WEST Line Section 20 Township 19S Range 37E NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLAN TO MIRU PULLING UNIT & TOH W/RODS & PUMP. REMOVE WELLHEAD & INSTALL BOP. TIH W/BOMB & OBTAIN STATIC BOTTOMHOLE PRESSURE. TOH W/TBG. TIH W/4-3/4" BIT & CLEAN OUT O.H. TO TD, 3995'. DRILL OUT AN ADDITIONAL 10'. TOH W/BIT. RU SCHLUMBERGER & LOG O.H. WITH GR/LDT LOG. ACIDIZE O.H. W/5000 GAL. NEFE DI HCL ACID. SWAB WELL. TIH W/TBG. REMOVE BOP, INSTALL WELL HEAD & TIH W/ PUMP & RODS. RDPV, CLEAN LOCATION & RESUME PROD. WELL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R.L. Wheeler, Jr. TITLE SUPV. ADM. SVC. DATE 2-9-93

TYPE OR PRINT NAME R.L. WHEELER, JR. TELEPHONE NO. (505) 393-214

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

FEB 12 1993