

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.O.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
---

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL  GAS WELL  OTHER

2. Name of Operator  
TEXACO Inc.

3. Address of Operator  
P. O. Box 728, Hobbs, New Mexico 88240

4. Location of Well  
UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM  
THE West LINE, SECTION 20 TOWNSHIP 19-S RANGE 37-E NMPM.

7. Unit Agreement Name  
---

8. Farm or Lease Name  
H. T. Mattern

9. Well No.  
1

10. Field and Pool, or Wildcat  
~~Eunice Monument~~  
Grayburg San Andres

11. Elevation (Show whether DF, RT, GR, etc.)  
3637' (GR)

12. County  
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

|  |   |   |   |
|--|---|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input checked="" type="checkbox"/>   | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     | COMMENCE DRILLING OPNS. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>            | CASING TEST AND CEMENT JOB <input type="checkbox"/> |   |
|  |   | OTHER _____ <input type="checkbox"/>                |   |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- RIGGED UP. PULL RODS AND PUMP. INSTALL BOP. PULL TUBING.
- CLEAN OUT TO 3965' (TD).
- TREAT OPEN HOLE 3826'-3965' W/4800 GALS 20% NEFE ACID IN 3 STAGES USING 400# ROCK SALT BETWEEN STAGES. FLUSH W/10# BRINE.
- INSTALL PUMPING EQUIPMENT. TEST AND PLACE ON PRODUCTION.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie W. Seedy TITLE Asst Dist Mgr DATE 8-23-84

APPROVED BY Oil & Gas Inspector TITLE \_\_\_\_\_ DATE AUG 28 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 27 1984

O.C.C.  
NOBBS OFFICE