

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

District I  
P.O. Box 1980, Hobbs, NM 88240

# OIL CONSERVATION DIVISION

District II  
P.O. Drawer DD, Artesia, NM 88210

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

District III  
1000 Rio Brazos Rd. Aztec, NM 87410

WELL API NO. 30 - 025 - 05683

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.  
B-2277

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit agreement Name  EAST EUMONT UNIT
2. Name of Operator OXY USA INC.	8. Well No. 50
3. Address of Operator P.O. Box 50250 Midland, TX 79710	9. Pool name or Wildcat EUMONT YATES SVN RVR QN
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>22</u> Township <u>19 S</u> Range <u>37 E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,647	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: TEMPORARILY ABANDONED <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD - 3996' PBTD - 3989' PERFS - 3932' - 3984'

MIRU PU 6/25/93, NDWH, NUBOP. RIH & TAG @ 3935', CO TO 3989'. POOH, RIH W/ PKR & SET @ 3878', LOAD ANN W/ 10# BW, TEST TO 500#, HELD OK, SWAB TEST WELL FOR NO OIL. POOH, RIH W/ CIBP & SET @ 3878', CIRC HOLE W/ CORR INH, RUN CSG INTR. TEST, HELD OK, POOH, NDBOP, NUWH, RDPJ. WELL TA'D 6/29/93.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Production Accountant DATE 09 03 93

TYPE OR PRINT NAME David Stewart TELEPHONE NO. 915 685-5717

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
 APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE SEP 09 1993


CONDITIONS OF APPROVAL, IF ANY: This Approval of Temporary Abandonment Expires 9-1-98

**RECEIVED**

**SEP 07 1993**

**USD HOUSE  
OFFICE**

PRINTED IN U.S.A.



cut out of ...  
limit # →

OK