

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

| | | |
|---|--|---|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | WELL API NO. 30-025-05725 |
| 1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | | 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 2. Name of Operator AMERADA HESS CORPORATION | | 6. State Oil & Gas Lease No. B-1962-1 |
| 3. Address of Operator POST OFFICE DRAWER D, MONUMENT, NEW MEXICO 88265 | | 7. Lease Name or Unit Agreement Name NORTH MONUMENT G/SA UNIT BLK. 11 |
| 4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>SOUTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line Section <u>29</u> Township <u>19S</u> Range <u>37E</u> NMMPM <u>LEA</u> County | | 8. Well No. 11 |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) | | 9. Pool name or Wildcat EUNICE MONUMENT G/SA |

| | |
|---|---|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |
| NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <u>Intent to convert to Injection Well.</u> <input checked="" type="checkbox"/> | SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1111

Move in and rig up pulling unit, reverse unit and air unit. Nipple down wellhead. Nipple up BOP. TIH w/underreamer, drill collars and tubing and underream f/3,808'-3,880'. TOH w/underreamer. Rig down air unit. Rig up Schlumberger and log the openhole with LDT/CNL.GR tools. Add perforations from 3,764'-3,808' with 2 JSPF. Rig down Schlumberger. TIH with treating packer on tubing to +/- 3,600'. Load casing-tubing annulus with fresh water. Set packer. Rig up acid company. Acidize well with 5,000 gal. 15% NEFE DI HCL w/3% DP-77MX Micellar solvent (using rock salt as diverting agent as needed). Swab/flow back load. TOH w/tubing and packer, laying down production tubing. Pickup and TIH w/2 3/8" coated injection tubing w/injection packer. Nipple down BOP. Nipple up injection wellhead assembly. Rig down and move out pulling unit. Clean and clear location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE Staff Assistant DATE 6-7-94

TYPE OR PRINT NAME Terry L. Harvey TELEPHONE NO. 393-2144

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE JUN 10 1994

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 03 1994

**OCU RECORDS
OFFICE**