

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-05742
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B 1533-122
7. Lease Name or Unit Agreement Name STATE 0
8. Well No. 4
9. Pool name or Wildcat EUMONT YATES 7RQ

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator Amerada Hess Corporation
3. Address of Operator P. O. Box 840, Seminole, Texas 79360-0840
4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>EAST</u> Line and <u>660</u> Feet From The <u>NORTH</u> Line Section <u>30</u> Township <u>19S</u> Range <u>37E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

08-19-97 THRU 09-04-97

MIRU REECO WELL SVC. FND. TBG. PRESS. @ 11#, CSG. PRESS. @ 19# & FLOW RATE @ 78 MCFPD. TIH W/MULESTAIL & STACKED OUT @ 3,454'. ATTEMPTED TO SPUD THRU W/NO SUCCESS. TIH W/SWAB & SET DWN. @ 3,454'. FND. NO FL & RCV'D. NO FLUID. PUMPED 5 BBLs. SOAPY 2% KCL DWN. TBG. & 5 BBLs. DWN. CSG. LET SET FOR 45 MINS. TIH W/MULESTAIL & SPUDDED DWN. TO 3,499'. COULD NOT MAKE ANY MORE HOLE. TIH W/1/3 SWAB CUP & FND. FL @ 2,950'. MADE 2 RUNS & RCV'D. 1-1/2 BBLs. THICK BLACK IRON SULFIDE EMULSION. TIH W/MULESTAIL & SPUDDED TO 3,528'. CI. TYLER WELL SVC. MIRU PULLING UNIT. RMV'D. WELLHEAD. INSTALLED BOP & TIH & CHK'D. FILL IN 6-5/8" CSG. @ 3,513'. FND. 121' OF FILL IN HOLE. TOH W/TBG. & PROD. EQUIP. TIH W/4-3/4" BIT ON 112 JTS. OF 2-3/8" OD TBG. DAVIS TOOL AIR DRILLING SVC. MIRU. EST. CIRC. LOWERED TBG. & BIT. DRLD. OUT FILL (CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 09/08/97  
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 915 758-6778

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: