

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1001 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05750 ✓
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1481-15

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name NORTH MONUMENT G/SA UNIT BLK. 10
2. Name of Operator AMERADA HESS CORPORATION	8. Well No. 14
3. Address of Operator DRAWER D, MONUMENT, NEW MEXICO 88265	9. Pool name or Wildcat EUNICE MONUMENT G/SA
4. Well Location Unit Letter <u>N</u> : <u>330</u> Feet From The <u>SOUTH</u> Line and <u>2310</u> Feet From The <u>WEST</u> Line	

Section <u>30</u>	Township <u>19S</u>	Range <u>37E</u>	NMPM	LEA	County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)					

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <u>REPAIR CASING</u> <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. I describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLAN TO MIRU PULLING UNIT & TOH WITH RODS AND PUMP. INSTALL BOP AND TOH WITH TUBING. RU LOGGING TRUCK AND RUN CBL TO LOCATE TOP OF CEMENT BEHIND 7" CASING. RUN PAL TO DETERMINE CONDITION OF PRODUCTION CASING. RU WIRELINE AND FREE POINT 7" CASING. CUT & PULL AS MUCH 7" CASING AS POSSIBLE ABOVE 9-5/8" SHOE. TIH W/LEAD SEAL CASING PATCH & NEW 7" 23#/FT. K-55 CASING. RIH W/PACKER & ATTEMPT TO ESTABLISH CIRCULATION RATE THROUGH HOLES IN CASING AT APPROXIMATELY 2890'. PERFORATE IF NECESSARY. RIH W/CEMENT RETAINER & SET ABOVE HOLES. ESTABLISH CIRCULATION. CIRCULATE INTERMEDIATE ANNULUS W/350 SKS OF CLASS "C" CEMENT & SQUEEZE OFF HOLES. DRILL OUT CEMENT & RETAINER. TEST CASING TO 500 PSI & OBTAIN CHART. CIRCULATE SAND OFF OF RBP. RIH W/RETRIEVING HEAD, RELEASE RBP & TOH. RIH W5-3/4" DRESS-OFF MILL & DRESS 3-1/2" FISH. RIH W/6-1/8" SHOE, 3 JTS 5-3/4" WASHPIPE, JARS, DRILL COLLARS & TUBING. ESTABLISH CIRCULATION W/AIR. WASHOVER TUBING DOWN TO TOP OF LANE WELLS FORMATION PACKER @ 3831'. RIH W/5-3/4" CUT-LIP GUIDE, 5-3/4" OVERSHOT, JARS, DRILL COLLARS & TUBING. LATCH ONTO FISH & ATTEMPT TO JAR FISH OUT OF THE HOLE. IF JARRING IS UNSUCCESSFUL, WASH OVER PACKER & THEN FISH. RIH W/BIT & CHECK FOR FILL. CLEAN OUT TO TD OF 3933'. (CON'T ON BACK)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. L. Wheeler, Jr. TITLE SUPV. ADM. SVC. DATE 3-18-93

TYPE OR PRINT NAME R. L. WHEELER, JR. TELEPHONE NO. (505) 393-2144

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE MAR 22 1993

CONDITIONS OF APPROVAL, IF ANY:

RU LOGGING TRUCK & RUN GR/CNL W/CALIPER ACROSS OPEN HOLE F/3780'-3933'. CHECK FOR SCALE ON FORMATION FACE. RU AIR UNIT & UNDERREAM OPEN HOLE TO REMOVE SCALE ON FORMATION FACE. RU LOGGING TRUCK & RUN GR/CNL WITH CALIPER ACROSS OPEN HOLE F/3780'-3933'. RIH WITH PRODUCTION EQUIPMENT & RETURN WELL TO PRODUCTION.

RECEIVED

MAR 1 1993

000 40833 00000