

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05754
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-5553
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 10
8. Well No.	9
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
Amerada Hess Corporation

3. Address of Operator  
P.O. DRAWER D, MONUMENT, NM 88265

4. Well Location  
Unit Letter I : 1980 Feet From The SOUTH Line and 660 Feet From The EAST Line  
Section 30 Township 19S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

**SUBSEQUENT REPORT OF:**

- PERFORM REMEDIAL WORK
- TEMPORARILY ABANDON
- PULL OR ALTER CASING
- OTHER: CONVERT TO INJECTION WELL.
- PLUG AND ABANDON
- CHANGE PLANS

- REMEDIAL WORK
- COMMENCE DRILLING OPNS.
- CASING TEST AND CEMENT JOB
- OTHER:
- ALTERING CASING
- PLUG AND ABANDONMENT

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1009

MIRU PULLING UNIT AND REVERSE UNIT. ND WELLHEAD. TOH & LAY DWN. RODS & PUMP. ND WELLHEAD. NU BOP. TOH W/TBG. TIH W/BIT, D.C.'S & TBG. DRILL RBP @ 3,901' & CLEAN OUT TO TD @ 3,940'. TOH W/BIT. RU SCHLUMBERGER & LOG THE OPENHOLE W/SONIC/CNL/GR TOOLS. RD SCHLUMBERGER. RU CEMENTERS. TIH W/TBG. OPEN ENDED & SPOT CMT. PLUG FR. 3,940' TO 3,910'. (USE OYSTER SHELLS TO ESTABLISH CIRC. IF NECESSARY). WOC 24 HOURS. TIH W/A SONIC HAMMER ON TBG. TO TD. RU ACID CO. ACIDIZE WELL W/5,000 GALS. 15% NEFE DI HCL W/3% DP-77MX MICELLAR SOLVENT. TOH W/SONIC HAMMER. TIH W/TBG. & PKR. SET PKR. AT +/-3,700'. SWAB/FLOW BACK LOAD. OBTAIN SHUT-IN BOTTOMHOLE PRESS. BEFORE BEGINNING INJ. EVALUATE FOR SAN ANDRES COMMUNICATION. TOH W/TBG. & PKR., LAYING DWN PRODUCTION TBG. P.U. & TIH W/2-3/8" LINED INJ. TBG. W/INJ. PKR. ND BOP. NU INJ. WELLHEAD ASSEMBLY. RDMO PU. CLEAN & CLEAR LOCATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 02-21-96  
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

**FEB 26 1996**