

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
 State Fee **X**

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR REEQUIP WELLS TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER- **Dual - Eumont Gas - Eunice Monument**

7. Unit Agreement Name

2. Name of Operator
GULF OIL CORPORATION

6. Form of Lease Name
B. V. Culp (NCT-B)

3. Address of Operator
P. O. Box 670, Hobbs, New Mexico 88240

9. Well No.
1

4. Location of Well
 UNIT LETTER **J** **2310** FEET FROM THE **South** LINE AND **2310** FEET FROM THE **East** LINE, SECTION **31** TOWNSHIP **19-S** RANGE **37-E** N.M.P.M.

10. Field and Pool, or Wildcat
Eumont Gas Eunice Monument

15. Elevation (Show whether DF, RT, GR, etc.)
3575' GR

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIATION WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER Acidize Eumont Gas; Temporarily Abandon Eunice Monument Zone <input checked="" type="checkbox"/> X	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3895' TD.

Pull producing equipment. Acidized Eumont Gas perms 3392-3528' with 2000 gals 15% NE HCL acid. Flushed w/18 bbls kill fluid. AIR 3.9 BPM. Max. Pressure, 1800#. ISIP 1000#, on vacuum in 1-1/2 minutes. Ran producing equipment and tested both zones. Pull rods & pump from Eunice Monument zone. Set 5-1/2" CIBP @ 3575' temporarily abandoning Eunice Monument zone. Ran 2-3/8" tbg & set @ 3552' & return Eumont Gas zone to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *A. P. Sikes, Jr.* TITLE Area Engineer DATE 05-03-78

APPROVED BY John Runyan TITLE Geologist DATE MAY 4 1978

CONDITIONS OF APPROVAL, IF ANY

7/1/78