

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 3002505771

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
NORTH MONUMENT G/SA UNIT
BLK. 15

1. Type of Well:
OIL WELL GAS WELL OTHER

8. Well No.
12

2. Name of Operator
Amerada Hess Corporation

9. Pool name or Wildcat
EUNICE MONUMENT G/SA

3. Address of Operator
P.O. BOX DRAWER D, MONUMENT, NM 88265

4. Well Location
Unit Letter L : 2310 Feet From The SOUTH Line and 330 Feet From The WEST Line
Section 31 Township 19S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
|---|---|---|---|
| PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | | CASING TEST AND CEMENT JOB <input type="checkbox"/> | |
| OTHER: _____ <input type="checkbox"/> | | OTHER: _____ <input type="checkbox"/> | |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU PULLING UNIT & REVERSE UNIT. TOH W/RODS & PUMP. ND WELLHEAD. NU BOP. TOH W/TBG. TIH W/TBG. & PKR. EST. PUMP-IN RATE & PRESS. ON PERFS. TOH W/TBG. & PKR. RU CEMENTERS. TIH W/7" CMT. RETAINER. SET RETAINER @ +/-3,600' & SQZ. CSG. LEAK W/APPROX. 200 SKS. CLASS 'C' CMT. W/2% CACL. MAX. PRESS. -1,000#. RD CEMENTERS. TOH W/TBG. RUN IN HOLE W/TBG. & 6-1/8" BIT. WOC 24 HRS. DRILL OUT RETAINER & CMT. TST. CSG. TO 500#. TOH W/TBG. & BIT. RU SCHLUMBERGER & PERF. W/4" CSG. GUN FR. 3,765'-3,780' W/2 SPF 180 DEG. PHASED (15 FEET, 31 HOLES TOTAL). RD SCHLUMBERGER. RU ACID CO. TIH W/SONIC HAMMER ON TBG. ACIDIZE WELL W/1,000 GAL. 15% NEFE DI HCL W/3% DP-77MX MICELLAR SOLVENT. MOVE TOOL ACROSS PERFS. 3,765'-3,780' THROUGHOUT ACID JOB. RD ACID CO. TOH W/SONIC HAMMER. TIH W/TBG. & PKR. SET PKR. @ +/-3,700'. SWAB BACK LOAD. RU SCHLUMBERGER & PERF. W/4" CSG. GUN FR. 3,601'-3,606', 3,612'-3,616', 3,626'-3,630', & 3,642'-3,666', 3,670'-3,706', 3,710'-3,746', 3,752'-3,756' W/2
(CONTINUED ON PAGE 2)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 01-22-96
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505 393-2144

(This space for State Use)

ORIGINAL SIGNED BY GARY WINK DATE JAN 30 1996
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:



NMGSAU #1512 - PAGE 2

SPF 180 DEG. PHASED (85 FEET, 177 HOLES TOTAL). RD SCHLUMBERGER. RU ACID CO. TIH W/SONIC HAMMER ON TBG. ACIDIZE WELL W/4,000 GAL. 15% NEFE DI HCL W/3% DP-77MX MICELLAR SOLVENT. MOVE TOOL ACROSS PERFS. THROUGHOUT ACID JOB. RD ACID CO. TOH W/SONIC HAMMER. TIH W/TBG. & PKR. SET PKR. +/-3,700'. SWAB BACK LOAD. TOH W/TBG. & PKR. TIH W/PROD. TBG. ND BOP. TIH W/RODS & PUMP. NU WELLHEAD. RDMO PULLING UNIT. CLEAN & CLEAR LOCATION.