

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05776
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name NORTH MONUMENT G/SA UNIT BLK. 15	
8. Well No.	5
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P.O. Box 840, Seminole, Texas 79360	
4. Well Location Unit Letter <u>E</u> : <u>1650</u> Feet From The <u>NORTH</u> Line and <u>330</u> Feet From The <u>WEST</u> Line Section <u>31</u> Township <u>19S</u> Range <u>37E</u> NMMP LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: CONVERT TO INJECTION WELL. ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1505
Plan to:

Order No. R-9596

MIRU PU & RU. TOH W/PROD. EQUIPMENT & TBG. SET RBP @ +\ -3,725'. CIRC. HOLE W/WATER & TST. CSG. TO 500 PSI. CHG. OUT WELLHEAD (IF NECESSARY). REMOVE RBP. TAG PBTD @ 3,860'. CIRC. HOLE CLEAN. PERF. 7" CSG. USING 4" HEGS (2 SPF 180 DEG. PHASING) FR. 3,782' - 3,794' (25 SHOTS). TIH W/SONIC HAMMER TO TD. WASH TO 3,764'. ACIDIZE NEW PERFS. ONLY FR. 3,782' - 3,794' W/600 GALS. HCL USING SONIC HAMMER. SWAB BACK LOAD. EVALUATE FOR SAN ANDRES COMM. BY SWAB TST. IF COMM. EXISTS. PLUG BACK WELL W/CMT. TIH W/INJ. EQUIPMENT. SET PKR. @ +\ -3,725'. RDMO. SI. OBTAIN 72 HR. SBHP DIP-IN.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Terry L. Harvey

TITLE SR. STAFF ASSISTANT

DATE 06-04-97

TYPE OR PRINT NAME

TERRY L. HARVEY

TELEPHONE NO. 505-393-2144

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

