

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

|                              |  |
|------------------------------|--|
| WELL API NO.                 | 30-025-05786   |
| 5. Indicate Type of Lease    | STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. | B-1128-1   |

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
AMERADA HESS CORPORATION

3. Address of Operator  
POST OFFICE DRAWER D, MONUMENT, NEW MEXICO 88265

4. Well Location  
Unit Letter E : 1980 Feet From The NORTH Line and 660 Feet From The WEST Line  
Section 32 Township 19S Range 37E NMPM LEA County

7. Lease Name or Unit Agreement Name  
NORTH MONUMENT G/SA UNIT  
BLK. 16

8. Well No.  
5

9. Pool name or Wildcat  
EUNICE MONUMENT G/SA

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

|  |   |   |   |
|--|---|---|---|
| <b>NOTICE OF INTENTION TO:</b>   |   | <b>SUBSEQUENT REPORT OF:</b>                        |   |
| PERFORM REMEDIAL WORK <input type="checkbox"/>   | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>              | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     | COMMENCE DRILLING OPNS. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  |   | CASING TEST AND CEMENT JOB <input type="checkbox"/> |   |
| OTHER: <u>Intent to convert to Injection Well.</u> <input checked="" type="checkbox"/> |   | OTHER: _____ <input type="checkbox"/>               |   |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1605

Move in and rig up pulling unit. TOH with rods and pump. Nipple down wellhead. Nipple up BOP. TOH with production tubing. Rig up Schlumberger and log the openhole with CNL/GR tools. Add perforations based on log data with 2 JSPF. Rig down Schlumberger. TIH with pinpoint injection packer on tubing to 3,897'. Test tubing to 3,000#. Rig up acid company. Acidize well with 4,000 gal. 15% NEFE DI HCL w/3% DP-77MX Micellar solvent. Swab/flow back load. TOH w/tubing and packer, laying down production tubing. Pick up and TIH w/2 3/8" coated injection tubing w/injection packer. Nipple down BOP. Nipple up injection wellhead assembly. Rig down and move out pulling unit. Clean and clear location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE Staff Assistant DATE 10-24-94

TYPE OR PRINT NAME Terry L. Harvey TELEPHONE NO. 393-2144

(This space for State Use) APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE OCT 28 1994

CONDITIONS OF APPROVAL, IF ANY:

R-9596