

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-05788

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
NORTH MONUMENT G/SA UNIT
BLK. 16

1. Type of Well:
OIL WELL GAS WELL OTHER

8. Well No. 282

2. Name of Operator
Amerada Hess Corporation

9. Pool name or Wildcat
EUNICE MONUMENT G/SA

3. Address of Operator
P.O. DRAWER D, MONUMENT, NM 88265

4. Well Location
Unit Letter I : 1980 Feet From The SOUTH Line and 660 Feet From The EAST Line
Section 32 Township 19S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: CONVERT TO INJECTION WELL. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1609

MIRU PULLING UNIT & REVERSE UNIT. ND WELLHEAD. TOH & LAY DWN. RODS & PUMP. ND WELLHEAD. NU BOP. TOH W/TBG. TIH W/BIT, D.C.'S & TBG. CLEAN OUT TO TD @ 3,914'. TOH W/BIT. RU SCHLUMBERGER & LOG THE OPENHOLE W/SONIC/CNL/GR TOOLS. TIH W/4" CSG. GUN. PERF. (INTERVAL TO BE DETERMINED FR. LOGS). RD SCHLUMBERGER. RU CEMENTERS. TIH W/TBG. OPEN ENDED & SPOT CMT. PLUG FR. 3,914' TO APPROX. 3,885'. (USE OYSTER SHELLS TO EST. CIRC. IF NECESSARY). WOC 24 HRS. TIH W/A SONIC HAMMER ON TBG. TO TD. RU ACID CO. ACIDIZE WELL W/4,000 GALS. 15% NEFE DI HCL W/3% DP-77MX MICELLAR SOLVENT. TOH W/SONIC HAMMER. TIH W/TBG. & PKR. SET PKR. AT +/-3,650'. SWAB/FLOW BACK LOAD. OBTAIN SHUT-IN BOTTOMHOLE PRESS. BEFORE BEGINNING INJ. EVALUATE FOR SAN ANDRES COMMUNICATION. TOH W/TBG. & PKR., LAYING DWN. PROD. TBG. P.U. & TIH (CONTINUED ON PAGE 2)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 02/21/96

TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE FEB 27 1996

CONDITIONS OF APPROVAL, IF ANY:

NMGSAU #1609 - CONTINUED - PAGE 2

WITH 2-3/8" LINED INJ. TBG. W/INJ. PKR. ND BOP. NU INJ. WELLHEAD ASSEMBLY. RDMO PULLING UNIT. CLEAN & CLEAR LOCATION.