

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee   
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CLEAN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL  GAS WELL  OTHER \_\_\_\_\_

2. Name of Operator  
W. K. Byrom

3. Address of Operator  
Box 147 Hobbs, NM88240

4. Location of Well  
UNIT LETTER E . 1650 FEET FROM THE N LINE AND 330 FEET FROM  
THE W LINE, SECTION 3 TOWNSHIP 20S RANGE 37E NMPM.

7. Unit Agreement Name \_\_\_\_\_

8. Farm or Lease Name  
J. W. Cooper G

9. Well No.  
1 3

10. Field and Pool, or Wildcat  
*Circle Monument*  
Indesignated

11. Elevation (Show whether DF, RT, GR, etc.)  
RT 3570

12. County  
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER _____ <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER _____ <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-2-81: Moved pulling unit on location, pulled rods and tubing. Rigged reverse unit to drill plug at 4200; ran DC & bit to bottom. Started drilling on CIBP, took 2 days to drill plug and cement. Cleaned 4 1/2" csg to 5400' to try Paddock Zone at some later date. Pulled tbg & DC out ran tbg back and started swabbing. Swabbed well dry in one day with show of gas and water. Spotted 1000 gals 15% NE acid over perf. from 4177 to 4214, let set for one hour. Started swabbing, getting 20 BWPH + 550 mcf/day. Put well on pump; changed 2" tbg to 2 1/2" & replaced 3/4" rods with 7/8" rods to handle large volume of water.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. W. Byrom TITLE Geologist DATE 9-11-81

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: