Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office OIL CONSERVATION DIVISION **DISTRICT I** WELL API NO. P.O. Box 1980, Hobbs NM 88241-1980 P.O. Box 2088 30-025-05908 DISTRICT II Santa Fe. New Mexico 87504-2088 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 FEE X STATE 🗌 **DISTRICT III** 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) NORTH MONUMENT G/SA UNIT 1. Type of Well: BLK. 21 WELL | WELL χ 2. Name of Operator 8. Well No. Amerada Hess Corporation 3 3. Address of Operator 9. Pool name or Wildcat P.O. DRAWER D, MONUMENT, NM 88265 EUNICE MONUMENT G/SA 4. Well Location 660 NORTH 1980 Unit Letter WEST Feet From The Line and Feet From The Line **20S** Section Township 37E LEA Range **NMPM** County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: CONVERT TO INJECTION WELL. 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. NMGSAU #2103 (08-27-96 THRU 09-13-96) TYLER WELL SVC. PULLED & LAID DWN. PROD. EQUIP. TOH W/TBG. RAN A BAKER LOC-SET RBP ON TBG. & SET THE PLUG @ 3,703'. STAR TOOL LOADED THE CSG. W/FW & CIRC. CLEAN W/170 BBLS. FW. STAR TOOL CIRC. CSG. CLEAN. TST'D. CSG. TO 580#. HELD OK. TOH W/TBG. & RETRIEVING HEAD. PUMPED 2 SKS. SAND ON TOP RBP. LOADED CSG. W/WATER. CLEANED OUT CELLAR DWN. TO 13" SUF. CSG. & PREP. TO CHG. OUT WELLHEAD. RAN 3 JTS. TBG. & CIRC. TOP OF 7" CSG. CLEAN W/FW. TOH W/TBG. RMV'D. OLD WELLHEAD & CLEANED OUT COLLAR DWN. TO 13" SURF. CSG. LOADED SURF. CSG. W/FW. INSTALLED NEW WELLHEAD FR. 9-5/8" INT. UP. INSTALLED BOP. SCHLUMBERGER RAN A CMT. BOND LOG FR. 1,630' TO THE SURF. DID NOT FIND ANY CMT. BEHIND THE PIPE. SHOT 4 HOLES IN THE 7" CSG. @ 1,225', 50' BELOW THE 9-5/8" INT. CSG. SHOE. STAR TOOL BROKE CIRC. THRU THE SHOT HOLE & CIRC. (CONTINUED) I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE SR. STAFF ASSISTANT SIGNATURE 09/16/96 TYPE OR PRINT NAME THREY TELEPHONE NO. (This space for State Use) Off (1) OCT 02 1996 APPROVED BY

TITLE

JCBN

CONDITIONS OF APPROVAL, IF ANY:

DATE