

U. S. Geological Survey  
P. O. Box 1157  
Hobbs, New Mexico

HOBBS DISTRICT

Operator: Union Texas Pet. Corp.

Well: 1 Britt B

Lease No. L.C. 031621(b)

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases".
2. The Hobbs office (telephone (505) 393-3612) is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e., ripping of pad and/or access road, reseeding, etc. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
5. If freepoint of 7" casing is not deeper than 2500 feet, contact USGS for approval of a change in plugging procedure. First alternate to be considered is to perforate 7" casing at approximately 2500 feet and cement squeeze.

If 7" casing is pulled from below 8-5/8" casing shoe, minimum cement plugs across shoe of 9-5/8" casing and in interval 1000 to 1100 should be 50 sacks. Plug across shoe of 9-5/8" casing must be tagged to assure it is in place.

RECEIVED

1971  
JAN 11 1971  
U.S. DEPARTMENT OF JUSTICE  
FEDERAL BUREAU OF INVESTIGATION