Submit 3 Copies to Appropriate

2

State of New Mexico

Form C-103 Revisied 1-1-89

Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION

District Office		OIL CONSERV	ATION DIVISION					
		P.O. B	ox 2088					
DISTRICT !		Santa Fe, Ne	w Mexico 87504-2088					
	, Hobbs, NM 88240	,						
DISTRICT II					API NO. (assigned by OCD on New Wells)			
P.O. Drawer Dd, Artesia, NM 88210					30-025-059	53		
DISTRICT III					e of Lease			
1000 Rio Brazos Rd., Aztec, Nm 87410				C. Ikilcate Typ		X FEE]	
				6. State Oil &	Gas Lease No.			
					N/A			
SUNDRY NOTICES AND REPORTS ON WELLS								
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"					7. Lease Name or Unit Agreement Name			
(FORM C-101) FOR SUCH PROPOSALS.)					G.C. MATTHEWS			
1. Type of W				1				
OIL	GAS							
WELL X WELL OTHER								
2. Name of Operator				8. Well No.				
CHEVRON U.S.A. INC.				12				
3. Address of Operator				9. Pool name or Wildcat				
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE				EUNICE MONUMENT				
4. Well Location						FACT		
Unit Letter	P	: 330 Feet From Th	888		Feet From The	EAST	_ Line	
Section	6	Township	20 S Range n(Show whether DF, RKB, RT, GR, etc.)	37E	NMP M	LEA	County	
		10. Elevatio						
			3556' GL					
11			Nature of Notice, Report, or Othe					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:								
PERFORM REM	EDIAL WORK PLU	G AND ABANDON X	REMEDIAL WORK]	ALTER CASING		J	
TEMPORARILY	ABANDON CHA	INGE PLANS	COMMENCE DRILLING OPNS.		PLUG AND ABAN.	Г	7	
PULL OR ALTER	3 CASING		CASING TEST AND CMT JOB	1			_	
			<u> </u>	ı			٦	
OTHER:			OTHER:				ı	
	 				· · · · · · · · · · · · · · · · · · ·	· 		
	Proposed or Completed Ope ate of starting any proposed		ails, and give pertinent dates, including					
esticated da	ite of starting any proposed	WOIK) SEE NOLE 1103.						
,	WE DRODOCE TO	DILIC AND ADANDON T	THE WELL AS FOLLOWS.					
WE PROPOSE TO PLUG AND ABANDON THIS WELL AS FOLLOWS:								
PLUG #1,PLACE 15 SX ON TOP OF CIBP @ 3525'. PLUG #2, SET CIBP @ 3300', LEAVE 15 SX ON TOP.								
								PLUG #3, PUT 30 SX PLUG F/2850-2950 (COVERS 9-5/8" SHOE).
PLUG #3, PUT 30 SX PLUG F/2830-2930 (COVERS 9-5/8 - SHOE). PLUG #4, PERF @ 450,SET RTNR & PMP 25 SX. CIRC 9-5/8 & 13-3/8 ANN. LEAVE 10 SX ON TOP.								
			25 5x. CINC 9-5/8 & 13-3	3/8 ANN. LE	AVE 10 SX C	M TOP.		
1	PLUG #5, SET 10	SX SURFACE PLUG.						
ALL PLUGS ARE CLASS-C NEAT MIXED AT 14.8 PPG, 1.32 CU/FT SX. DISPLACE								
		PG MUD LADEN FLUID.						
			TVELLOCATIONS DIACE	O A BAADUT	D 0			
		•	EVEL LOCATION, PLACE F	WA WARKE	nα			
(CHANGE STATUS	OF WELL TO PLUGGED	AND ABANDONED.			- 10 g ∦ .		
						.		
			1, 1,		100	200		
				v +5 .		AT A SALA		
I hereby certify	that the information shove	is trye and complete to the best of m	v knowledge and belief			_		
SIGNITURE	Mit	LAO TITLE	TECHNICAL ASSISTANT	DATE:	12/20/93			
-	· Jua	/ W				···.		
TYPE OR PRINT				TELEPHONE NO. (915)687-7436				
	ORIGINA	AL SIGNED BY JERRY SE	NOTE					
DISTRICT I SUPERVISOR				DATE JAN 05 1994				
APPROVED BY				DATE VAIN 0 3 1994				

CONDITIONS OF APPROVAL, IF ANY: