

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State ☐ Fee ☒
5b. State Oil & Gas Lease No.
6. Unit Agreement Name
7. Name of Lease Name J. R. Phillips
8. Well No. 6
9. Field and Pool, or Wildcat Monument Abo
10. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSAL TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
SEE APPLICATION FOR PERMIT - FORM C-101 FOR SUCH PROPOSAL.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator TEXACO Inc.
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER E 660 FEET FROM THE West LINE AND 1897 FEET FROM THE North LINE, SECTION 6 TOWNSHIP 20-S RANGE 37-E NEIGH.

15. Elevation (Show whether DF, RT, GR, etc.)
3576' (DF)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPER. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOBS ☐
OTHER ☐	OTHER ☒ Addl. Abo perms.
PLUG AND ABANDON ☐	ALTERING CASING ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pull rods & pump. Install BOP. Pull tubing.
2. Clean out to 7760. (TD). Log well.
3. Perforate 5½" csg w/2 JSPF @ 7371, 77, 7420, 56, 69, 74, 79, 96, 7531, 40, 54, 80, 97, 7620, 39, 46, 59, 66, 80, 86, 7703, & 7710.
4. Set RBP @ 7715 & pkr @ 7627, Acidize perms 7620-7710 w/2000 gals. 15% HCl acid in 2 equal stages using 400# rock salt between stages. Flushed w/46 bbls. brine wtr.
5. Reset RBP @ 7624 & pkr @ 7395. Acidize perms 7420-7639 w/5000 gals. 20% HCl acid in 3 stages using 2100# rock salt.
6. Reset RBP @ 7395 & pkr @ 7050. Acidize perms 7109-7326 w/1500 gals. 15% HCl acid & 30 ball sealers. Flushed w/42bbls. brine wtr.
7. Install production equipment. Test & place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Jerry Sexton* TITLE **Asst. Dist. Supt.** DATE **1-25-80**

Orig. Signed by
Jerry Sexton

APPROVED BY *Dist. 1. Supv.* TITLE _____ DATE **JAN 29 1980**

CONDITIONS OF APPROVAL, IF ANY: