Form 9-331 (May 1963)	UNILLD STATES EPARTMENT OF THE INTERI GEOLOGICAL SURVEY	SUBMIT IN TRIPLICATE* (Other instructions on reverse side)	Form approved. Budget Bureau No. 42-R1424.  5. LEASE DESIGNATION AND SERIAL NO.  LC - 031621 (a)
	Y NOTICES AND REPORTS ( of proposals to drill or to deepen or plug be "APPLICATION FOR PERMIT—" for such parts		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. OIL X GAS WELL X	OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR			8. FARM OR LEASE NAME
Union Texas Petroleum Corporation 3. ADDRESS OF OPERATOR			Britt 9. WELL NO.
4000 N. Big Spring, Suite 500, Midland, Texas 79705  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface  Unit Letter C, 660' FNL & 1980' FWL			2
			10. FIELD AND POOL, OR WILDCAT  Youment - Grayburg
			11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
14. PERMIT NO.	15. ELEVATIONS (Show whether DF.		Sec. 7, T-20-S, R-37-E
14. PERMIT NO.	3563' G.L.	RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
16.			Lea   New Mexico
	Check Appropriate Box To Indicate N  E OF INTENTION TO:		
٢			NT MEPORT OF:
TEST WATER SHUT-OFF FRACTURE TREAT	PULL OR ALTER CASING MULTIPLE COMPLETE	WATER SHUT-OFF	REPAIRING WELL
SHOOT OR ACIDIZE	ABANDON*	FRACTURE TREATMENT SHOOTING OR ACIDIZING	ALTERING CASING ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other)	
(Other)		Completion or Recomplet	! multiple completion on Well ion Report and Log form.)
17. DESCRIBE PROPOSED OR COM proposed work. If well nent to this work.) *	PLETED OPERATIONS (Clearly state all pertinent is directionally drilled, give subsurface locations)	details, and give pertinent dates, in ons and measured and true vertical	cluding estimated date of starting any depths for all markers and zones perti-
1. MIRUSU, Notify	NMOCC., USGS.		
2. POH with produ	ction equipment and fill an	nulus with 10# gal. mu	d laden fluid.
<ol> <li>Set cement ret w/150" sx C1.</li> </ol>	ainer in 7" casing @ 3400' "C" cement containing 1% Ca	and squeeze perforation ${ m Cl}_2.$	n 3453' - 3538'
4. PUH and perfor 7" casing w/75	ate casing @ 2425'. Set resx. Cl. "C" containing 1% C	tainer @ 2325± and cem a Cl <sub>2</sub> . Lagran 100.	ent squeeze outside
	ment plug 306' to 206'.		T. T. T.
6. Spot 20 sx. cer	ment plug 50 to surface.		
7. Cut off casing	, set permenant well marker	and clean up location	
18. I hereby certify that the	oregoing is true and correct		
SIGNED	Magnir TITLE Regi	il. Compl. Coord.	DATE _6-14-84
(This space for Federal or	State office use)	•	
	表现 PAS	A Mana (1) Lebau North (1)	DATE 12.31.84
CONDITIONS OF APPRO		COUNTY . L	DATE //