Form 9-331 UN' .D STATES SUBMIT IN TRIPLL E* (May 1963)P. (Other Instructions on re- PORTMENT OF THE INTERIOR verse side)	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.
GEOLOGICAL SURVEY	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	LC-031621 (a) 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS WELL X OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
Union Texas Petroleum Corporation 3. ADDRESS OF OPERATOR	Britt 9. WELL NO.
Unit Letter B. 660' FNL & 1980' FEL	4 10. FIELD AND POOL, OR WILDCAT EURICE-Monument 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA Sec. 7, T-20-S, R-37-E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
3556 G.L.	Lea New Mexico
16. Check Appropriate Box To Indicate Nature of Notice, Report, of Ot	ther Data
NOTICE OF INTENTION TO: SUBSEQUE	ENT REPORT OF:
Completion or Recomplet	ALTERING CASING ABANDONMENT* of multiple completion on Well tion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, i proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical nent to this work.)* 1. MIRUSU. Notify NMOCC and USGS.	depths for all markers and zones perti-
 POH with production equipment. Fill well annulus w/10# ga Set cement retainer @ 3580'± and squeeze perforation 3680- 	
4. Perforate casing 2480' w/4 holes. Set cement retainer @ 24 sx. C1 "C".	
5. Perforate casing @ 250' and squeeze w/100 sx. Cl "C" leavingide 7' casing.	ring 20 sx. of cement
6. Spot 20 sx. cement plug 50' to surface.	
7. Cut off casing, weld on cap, set well marker and clean up	location.
SIGNED SIGNED TITLE Regul. Compl. Coord.	DATE <u>6-18-84</u>
APPROVED BY	DATE 12-31-84