

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

4-MOCC
1-File

HOBBS OFFICE O. C. O.
Dec 17 1 29 AM '69

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>	
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name T. ANDERSON	
9. Well No. 2	
10. Field and Pool, or Wildcat MONUMENT	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER- ☐

2. Name of Operator
GIFTY OIL COMPANY

3. Address of Operator
P.O. BOX 249, HOBBS, NEW MEXICO 88240

4. Location of Well
UNIT LETTER **I**, **1980** FEET FROM THE **South** LINE AND **660** FEET FROM
East LINE, SECTION **8** TOWNSHIP **20** RANGE **37** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3550 D.F.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set 7" 24# Cement Retainer @ 3695', Squeeze the perforations 3704-25' with 100 Sacks Class C with 2/10% Halide 9 and 50 sacks Class C with 2# salt and 5# Sand per sack. Perforate the Grayburg San Andres @ 3639, 49, 51, 62, 70, 72, 74, 79, and 81 with 1 hole per depth. Acidize with 750 gallons 15% HCl Acid and Ball Sealers.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *C. A. Wade* TITLE **Area Superintendent** DATE **December 16, 1969**

APPROVED BY *Leslie A. Clements* TITLE **Gas Inspector** DATE **12 18 1969**

CONDITIONS OF APPROVAL, IF ANY:
/dh

1990

; .

• •