

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
A-1212	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> PXA		7. Unit Agreement Name
2. Name of Operator Amoco Production Company		8. Farm or Lease Name State A2 RA/A
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240		9. Well No. 11-Y
4. Location of Well UNIT LETTER <u>C</u> <u>810</u> FEET FROM THE <u>North</u> LINE AND <u>2030</u> FEET FROM THE <u>West</u> LINE, SECTION <u>4</u> TOWNSHIP <u>19-S</u> RANGE <u>38-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Wildcat Yates
15. Elevation (Show whether DF, RT, GR, etc.) 3639' DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in service unit 4-19-83. Pulled tubing and packer. Ran a cast iron bridge plug to 2190' from surface and could not go down. Pulled bridge plug and stuck 1805' from surface. Drilled out cast iron bridge plug. Spotted 150 sacks class C cement with additives at 2617' from surface. Tagged cement to 2115' from surface and circulated hole with mud. Perforated 1525'-26' with 4 SPF and established circulation. Set a cement retainer at 1480'. Cemented with 145 sacks class C neat cement and circ. 4 sacks. Spotted 10 sacks class C to surface. Erected dry hole marker. Moved out service unit 4-22-83.

O+5-NMOCD,H 1-HOU 1-F. J. Nash, HOU 1-CLF

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cathy L. Forman TITLE Assist. Admin. Analyst DATE 5-3-83

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE JUN 29 1983

CONDITIONS OF APPROVAL, IF ANY: