## STATE OF NEW MEXICO ENERGY AND MUNERALS DEPARTMENT

DISTRIBUTION		Ĭ
SANTA FX		
711.2	- [	<u> </u>
U.3.G.5.		
LAND OFFICE	1	1_
04534703	i	

## OIL CONSERVATION DIVISION

Form	C - 1	03	
90015	c d	1/1-	1 - 1

DISTRIBUTION	P. O. BOX 2088	Revised 10-1-7		
SANTA FX	SANTA FE, NEW MEXICO 87501			
71L2		State Type of Lease		
LAND OFFICE	•	S. State Off & Gas Leaso No.		
OZETATOR I		J. State On G dad Et and Her		
		minnennine.		
SUNDRY	NOTICES AND REPORTS ON WELLS  SALE TO DELICE ON TO DELICE OF PLUS BALE TO A DIFFERENT RESERVOIR.  4 TOR FERMIT - TO TORNE CIVILIES AND THE PROPOSALES!			
USE "APPLICATIO	4 TOR FERMIT -" FORTE C-1011 FOR SUCH PROPODALS.1	7. Unit Agreement Name		
OIL GAS	OTHT0-			
WELL X WELL I	OTHER-	d. Farm or Lease Nume		
	nv	South Hobbs Unit (GSA)		
Amoco Production Compar	TY .	91 No.		
P. O. Box 68, Hobbs, Ne	ew Mexico 88240	29		
4. Location of Well	SW TICKTOO GCZ TO	10. Field and Pool, or arideat		
	1985 FEET FROM THE North LINE AND 1988 FEET	Hobbs (GSA)		
•				
East Une section	TOWNSHIP 19-S HANGE 38-E	MON. (		
THE				
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County		
	3634' KB	Lea ()		
To: Check A	Appropriate Box To Indicate Nature of Notice, Report o	r Other Data		
NOTICE OF IN	TENTION TO: SUBSEQU	JENT REPORT OF:		
·		,		
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABAHCONMENT		
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	, L-		
	OTHER			
OTHE -		,		
17. Describe Proposed or Completed Op	erations (Clearly state all pertinent details, and give pertinent dates, inc	luding estimated date of starting any propose		
· work) SEE RULE 1103.				
Propose to expose addi	tional pay by deepening, perforating and acid	lizing as follows:		
Move in and rig up service unit. Install blow out preventer and pull rods, pump and tubing. Run in hole with bit for 5-1/2", 15.5# casing. Deepen well to 4240'. Pull out of hole.				
Run in hole with bit f	for $5-1/2$ ", $15.5$ # casing. Deepen well to $4240$	0. Pull out of hole		
Run in hole with casin	ng gun and perf zone II and III intervals at 4	15 E# casing Set nacker		
001 1100   06   111 + 16	S O ICOE DOM IN MAIA WITH HACKER TOR DELLA .	13.Jπ Casing. Jee packer		
at 4020', load backsid	de and pressure up to 300 PSI. Acidize perfs	-asian inhihitan in 3 stages		
4200'-40' with 3000 ga	ils 15% NE HCL acid containing I gai/1000 com	.081011 Illitation in 3 scades		
-+ 2 / DDM and may nre	secure at INN PSI as follows:	- · · · · · · · · · · · · · · · · · · ·		
Dumn 1000 dale acid r	numn a block consisting of 300# graded rock sa	alt with 100# 100 mesh sait		
:- 200 gale 20# galla	ad bring and repeat both numping Steus twice.	riusii actu to open note		
and avon displace with	a 30 bbl using fresh water. Release Dacker ar	la batt our of note. Kan		
in hole with mud ancho	or, perforated sub, seating nipple and tubing	Idila illua aliction at 42002.		
Rig down and move out	service unit. Pump test to evaluate product	ion characteristics.		
· ·				
0+4-NMOCD,H 1-HOU	1-F. J. Nash 1-SUSP 1-PJS 1-Petro Lewis	5		
		•		
13. I hereby certify that the information	n above is true and complete to the best of my knowledge and belief.			
(-) f ()	Accist Admin Analyst	4-22-83		
TICHEO Y Y LLI JE	Assist. Admin. Analyst	DATE		
OPIGINAL SIGN	NED BY JERRY SEXTON	ΔPR 26 1983		
CAPHINAL SIGN	TEN DI JERRI BERLUM	UPR / N IMM		

DISTRICT I SUPERVISOR

CONDITIONS OF APPROVAL, IF ANYI

APR 25 1983