



Address... Box 68, Hobbs, New Mexico



NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS



Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON Tests Re-quired by NMOCC (Other)	X

September 28, 1953
(Date)

Hobbs, New Mexico
(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Stanolind Oil and Gas Company
(Company or Operator)

H. D. McKinley NW/5
(Lease)

(Contractor)

Well No. 1 in the NE 1/4 NW 1/4 of Sec. 5

T 198, R 38E, NMPM, Hobbs Pool, Lea County.

The Dates of this work were as follows: September 10, 1953

Notice of intention to do the work (~~was~~ (was not) submitted on Form C-102 on _____, 19____, and approval of the proposed plan (was) (was not) obtained.
(Cross out incorrect words)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Casing pressure 100 psig

Tubing pressure 100 psig

No leaks indicated by attached temperature survey.

Plan to measure pressure on annular space between 6-5/8" and 10-3/4" and between 10-3/4" and 16". If pressure exists plan to run temperature survey with annulus open to atmosphere.

Witnessed by Rowland Laxson
(Name)

Stanolind Oil and Gas
(Company)

Roustabout
(Title)

Approved:

OIL CONSERVATION COMMISSION


E. J. Fisher
(Name)

(Title)

(Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name *Wm. H. Fisher*
Position Field Engineer
Representing Stanolind Oil and Gas
Address Box 68, Hobbs, New Mexico



NEW MEXICO OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Form C-110
Revised 7/1/55

(File the original and 4 copies with the appropriate district office)

CERTIFICATE OF COMPLIANCE AND AUTHORIZATION
TO TRANSPORT OIL AND NATURAL GAS

Company or Operator Pan American Petroleum Corporation Lease H. D. McKinley

Well No. 1 Unit Letter C S 5 T 19 R 38 Pool Hobbs

County Lea Kind of Lease (State, Fed. or Patented) Patented

If well produces oil or condensate, give location of tanks: Unit F S 5 T 19 R 38

Authorized Transporter of Oil or ~~Condensate~~ Shell Pipe Line Corporation

Address Box 1598 Hobbs, New Mexico

(Give address to which approved copy of this form is to be sent)

Authorized Transporter of Gas Phillips Petroleum Company

Address Box 758 Hobbs, New Mexico

(Give address to which approved copy of this form is to be sent)

If Gas is not being sold, give reasons and also explain its present disposition:

Reasons for Filing: (Please check proper box) New Well ()

Change in Transporter of (Check One): Oil () Dry Gas () C'head () Condensate ()

Change in Ownership () Other (x)

Remarks: (Give explanation below)

Change of operating name from "Stanolind Oil and Gas Company" to
"Pan American Petroleum Corporation" effective February 1, 1957.

The undersigned certifies that the Rules and Regulations of the Oil Conservation Commission have been complied with.

Executed this the 24th day of January 19 57

By Robert Neumann

Title Field Superintendent

Company Pan American Petroleum Corporation

Address Box 68

Hobbs, New Mexico

Approved JAN 29 1957 19 57

OIL CONSERVATION COMMISSION

By E. Fischer

Title Engineer District 1

• \mathcal{L}_1 norm is used to calculate the distance between two vectors.

• The distance between two vectors is calculated as the sum of absolute differences.

• \mathcal{L}_2

• \mathcal{L}_2 norm is used to calculate the distance between two vectors.

• The distance between two vectors is calculated as the square root of the sum of squared differences.

• \mathcal{L}_2 norm is used to calculate the distance between two vectors.

• \mathcal{L}_2 norm is used to calculate the distance between two vectors.

• The distance between two vectors is calculated as the square root of the sum of squared differences.

• \mathcal{L}_2 norm is used to calculate the distance between two vectors.

• \mathcal{L}_2 norm is used to calculate the distance between two vectors.

• \mathcal{L}_2 norm is used to calculate the distance between two vectors.

• The distance between two vectors is calculated as the square root of the sum of squared differences.

• \mathcal{L}_2

• \mathcal{L}_2 norm is used to calculate the distance between two vectors.