

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 20811  
SANTA FE, NEW MEXICO 87501

Form O-103  
Revised 12-1-77

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL OIL WELLS FOR SUCH PURPOSES.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: <u>PXA</u>	2. Unit Agreement Name
2. Name of Operator <u>Amoco Production Company</u>	8. Name of Lease Name <u>South Hobbs (GSA) Unit</u>
3. Address of Operator <u>P.O. Box 68 Hobbs NM 88240</u>	9. Well No. <u>28</u>
4. Location of well UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>5</u> TOWNSHIP <u>19-S</u> RANGE <u>38-E</u> N.M.P.M.	10. Field and Pool, or Allotment <u>Hobbs GSA</u>
15. Elevation (show whether DF, RT, GL, etc.) <u>3624' DF</u>	11. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK   
TEMPORARILY ABANDON   
PULL OR ALTER CASING   
OTHER

PLUG AND ABANDON   
CHANGE PLANS   
OTHER

SUBSEQUENT REPORT OF:

REMEDIAL WORK   
COMMENCE DRILLING OPERATIONS   
CASING TEST AND CEMENT JOBS   
OTHER

ALTERING CASING   
PLUG AND ABANDONMENT   
OTHER

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to PXA as follows:  
POH with rods, pump, and tbg. RIH and set cmt. retainer at 3800'. Pump 100 sxs of class C' neat followed by 100 sxs class C' w/additives. Tail in with class C' neat to obtain a squeeze of 1500 psi. Cap cmt retainer with 25 sxs class C' neat. Spot 24 bbls of 10# brine with 25 lbs gel per bbl. Spot 50 sxs class C' neat across interval 2625'-2975'. Spot 34 bbls of 10# brine with 25 lbs gel/bbl. Spot 50 sxs class C' neat 1250'-1600'. Spot 33 bbls of 10# brine with 25 lbs gel/bbl. Perforate 200'-201' with 4 DPJSPF using a 4" cog. gun. Establish circulation 9+5 NMCD, H 1-J.R. Barnett, Hou Rm 21.156 1-F.J. Nash, Hou Rm 4.206 1-GCC 1-Retro-Lewis

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

Mary C. Clark TITLE Asst. Admin. Clerk DATE 10/31/84

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE YEAR 1984

OCT 31 1984

through the 13" - 9 5/8" annulus. Pump 150 s/w class 'c' neat  
down the 6 5/8" csg and circulate through the 13" - 9 5/8" annulus.  
Leave csg full to surface with cmt. Weld on cap and erect  
PXA marker.

\* Notify NMCD prior to setting plugs

RECEIVED

OCT 12 1984

G. B.  
HOSES COMPANY