## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	T	
PISTRIBUTION		
SANTA PE		
PILE		
U.S.O.S.		
LAND OFFICE		
DEFRATOR		i ·

## OIL CONSERVATION DIVISION

Form C-103

SANTA PE	P. O. BOX 2088 Revised 10- SANTA FE, NEW MEXICO 87501	
PILE	SANTA PE, NEW MEXICO 07301	Sa. Indicate Type of Lesse
U.S.O.S.		State X Fee
LAND OFFICE		5. State Oil 6 Gas Lease No.
OPERATOR		A-1646
		mmminink
SUNDRY NOTICES AND REPORTS ON WELLS  100 HOT USE THIS FORM FOR PROPOSALS TO CALLED TO A DIFFERENT RESERVOIR.		
1.		7, Unit Agreement Name
OIL CAS WELL	other Injection	
2. Name of Operator		8. Form or Lease Name
AMOCO PRODUCTION COMPANY		South Hobbs (GSA) Unit
J. Address of Operator	•	9. Well No.
P. O. Box 68,	Hobbs, NM 88240	113
4. Location of Well		10. Field and Pool, or Wildcat
C.	1650 FEET FROM THE North LINE AND 1650 FEET FR	Hobbs (GSA)
UNIT LETTER	FEET FROM THE	
East	6 19-S 38-E NAME	(
THE EAST LINE, SE	CTIONTOWNSHIP	
Milliannin	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3625' GL	Lea
16. Chan	k Appropriate Box To Indicate Nature of Notice, Report or	Other Data
	FINTENTION TO: SUBSEQUE	NT REPORT OF:
NOTICE OF	o INTENTION TO.	
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS CASING TEST AND CEMENT JOB	
PULL OR ALTER CASING	OTHER	
•		•
OTHER		
17. Describe Proposed or Complete	d Operations (Clearly state all pertinent details, and give pertinent dates, include	ing estimated date of starting any propos
work) SEE RULE 1103.		ent retainer, tubing.
Moved in service ur	nit 10-11-83. Pulled tubing and packer. Ran cem	rilled out to 4175'.
& set retainer at <sup>2</sup>	1104'. Cement squeezed with 325 sacks cement. D	ed with 100 sacks cement.
Drilled out to 4240	o'. Found leak at 3793'-3810'. Spotted 17 sacks	squeezed with 100 sacks
3837'. Ran cement	retainer, tubing & retainer set at 4207'. Cement to 4243'. Ran packer, tubing and packer set at	3875' Pressure tested
cement. Drilled ou	t to 4243'. Ran packer, tubing and packer set at	urned to injection
packer at 500 psi a	nd OK. Moved out service unit 11-7-83. Well ret	arried to injection
11-8-83.	•	
	D = 0 + D = 01 1F0 1 F 1 Mach UOII Dm /	206 1_SHSP 1_P.1S
0+4-NMOCD,H 1-HOU	R. E. Ogden Rm. 21.150 1-F. J. Nash, HOU Rm. 4.	200 1-3031 1-103

18. I hereby certify that the information above is true and cumplete to the best of my knowledge and belief. ORIGINAL SIGNED BY JERRY SEXTON

1-Petro Lewis

RECEIVED
AN 20 1984
CRES OFFICE