

Stanolin 2 - State # 87E9-19-38

We did not receive BG 103 & 106 for the $10\frac{3}{4}$ " pipe for this well and I did not receive notice of their intention to test this pipe due to a misunderstanding of the superintendent for the Stanolin. He was under the impression that we did not require this test for this string. Although they tested it for their own satisfaction

J. D. Hunter.