

OF COPIES RECEIVED	
DISTRIBUTION	
SANITARY	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>Charles E. Hannon</b>		8. Farm or Lease Name <b>American Nat'l. Ins. Co.</b>
3. Address of Operator <b>P. O. Box 5753, Midland, Texas</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>D</b> , <b>947.8</b> FEET FROM THE <b>west</b> LINE AND <b>790</b> FEET FROM THE <b>north</b> LINE, SECTION <b>18</b> TOWNSHIP <b>19-A</b> RANGE <b>37-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Eunice Monument (G-SA)</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3716' DF</b>		12. County <b>Lee</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Well to be plugged in the following steps:**

- (1) Cast iron plug to be set @ base of casing (3900') with 35 ft. cement on top of plug.
- (2) 100 ft. plug @ cut-off point in and out of stub.
- (3) 100 ft. plug to isolate salt section - top and bottom if not behind pipe.
- (4) 100 ft. plug @ shoe of surface pipe (329').
- (5) 10 sack plug @ surface with marker (4" pipe with 6' above the surface).

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles E. Hannon TITLE OWNER DATE 8/20/74

APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE AUG 26 1974