

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Benitos Rd., Aztec, NM 87410

WELL API NO.  
30-025-12469

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.  
B869

7. Lease Name or Unit Agreement Name

State F

8. Well No.  
1

9. Pool name or Wildcat  
Eunice Monument G/SA

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER Dual Compl.

2. Name of Operator  
Amerada Hess Corporation

3. Address of Operator  
Drawer D, Monument, New Mexico 88265

4. Well Location  
Unit Letter M : 660 Feet From The West Line and 660 Feet From The South Line  
Section 36 Township 19S Range 36E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: Abandon G/SA Zone <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to MIRU pulling unit & TOH w/rods & pump. TOH w/1-1/2" tbg. Remove well head & install BOP. TOH w/3-1/2" tbg. & pkr. Run gauge ring & junk basket to + 3720' & TOH. TIH w/CIBP & set at + 3720'. Dump bail 20' cement on top CIBP & Abandon G/SA Zone. TIH w/pkr. set at + 3200' & circ. csg. annulus w/pkr. fluid. RDPU & clean location. Resume prod. fr. Eumont Yates 7RQ Zone as single producer.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. L. Wheeler, Jr. TITLE Supv. Adm. Svc. DATE 12-4-91

TYPE OR PRINT NAME R. L. Wheeler, Jr. TELEPHONE NO. 393-2144

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE 12-4-91

CONDITIONS OF APPROVAL, IF ANY: