

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input checked="" type="checkbox"/> WELL GAS <input type="checkbox"/> WELL OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation		8. Farm or Lease Name State "F"
3. Address of Operator Drawer D, Monument, New Mexico 88265		9. Well No. 5
4. Location of Well UNIT LETTER N 785 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 19S RANGE 36E N.M.P.M.		10. Field and Pool, or Wildcat Eunice Monument-G/SA
15. Elevation (Show whether DF, RT, GR, etc.) 3590' DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Progress Report

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-2-87 to 12-10-87

RU pulling unit & pulled rods & pump. Installed BOP, released TAC & pulled tbg. Ran 5-1/2" CIBP & set at 7170'. Ran pkr. set at 4368' & press. tested CIBP to 500#. Held OK. Recovered pkr., ran dump bailer & dumped 4 sks. (35') cement on top of CIBP at 7170'. Abandoned Abo Zone. TIH & ran GRN/CCL log across Grayburg San Andres Zone fr. 5940' to 3300'. McCullough perf. Grayburg San Andres Zone 5-1/2" csg. w/3-1/8" Select Fire csg. gun w/2SPF at the following intervals: 3579', 3586', 3600', 3621', 3635', 3651', 3666', 3675', 3681', 3694', 3705', 3720', 3731', 3745', 3747', 3753', & 3756'. Total 34 shots. Swabbed. Ran tbg., removed BOP & TIH w/pump & rods. Began pumping well on 12-10-87.

Recompletion reports to follow upon establishment of production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R. L. Whelan, Jr.</u>	TITLE <u>Supv. Adm. Svc.</u>	DATE <u>1-6-88</u>
Orig. Signed by Paul Kautz Geologist		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		