

COPIES RECEIVED		
TRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
B-869

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name State F
3. Address of Operator Drawer "D" - Monument, New Mexico 88265	9. Well No. 5
4. Location of Well UNIT LETTER <u>N</u> <u>785</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>19-S</u> RANGE <u>36-E</u> NMPM.	10. Field and Pool, or Wildcat Monument McKee-Ellenbg
15. Elevation (Show whether DF, RT, GR, etc.) 3590' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>T. A.</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-67: Unable to establish production from McKee-Ellenburger zone, closed in and T. A.

7-68: Set BP at 7800' w/one sack cement on top. McKee-Ellenburger zone P & A

Perforated Blinebry zone 5620' to 5712'. Treated w/acid. Nonproductive. Squeezed perfs 5620' to 5712' w/150 sacks cement. Drilled cement and perfs 5691' to 5711'. Acidized w/1500 gals 15% NE. Tested nonproductive Closed in and T. A. 7-6-68

Plan to reevaluate Blinebry and G-SA zones if nonproductive, plug and abandon Work to be done in 3rd quarter, 1975

Expires 10/1/75

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Supvr. Admin. Services DATE 10-11-74

APPROVED BY [Signature] TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____