

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION, C.

JUL 1 8 35 AM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. R-869
7. Unit Agreement Name
8. Farm or Lease Name State "7"
9. Well No. 5
10. Field and Pool, or Wildcat Monument-McKee- Ellenburger Gas
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Amerada Petroleum Corporation
3. Address of Operator P. O. Box 668 - Hobbs, New Mexico
4. Location of Well UNIT LETTER N , 785 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 19-S RANGE 36-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3580' DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pull tubing and packer. Set bridge plug at 7800'. Dump 1 sack cement on bridge plug. Perforate 5-1/2" casing from 5620' to 5712' with one shot per foot. Acidize perforations with 7500 gals. 15% Unisol acid in three stages with rock salt diverter. Swab acid water. Pull tubing and packer. Run production string and complete as new oil well in Blinebry Pool.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>[Signature]</i></u>	TITLE <u>District Superintendent</u>	DATE <u>6-28-68</u>
APPROVED BY <u><i>[Signature]</i></u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		