STATE OF NEW MEXICO ENERGY AND MAJERALS DEPARTMENT

88. 87 687128 BCCCIVCS		
DISTRIBUTION	1	
SANTA FE	1	
FILE		
U.S.O.S.		1
LAND OFFICE	1	
OPPRATOR	1	

U.L CONSERVATION DIVISION

DISTRIBUTION	P. O. BOX 2088	Form C-103	
SANTA FE	SANTA FE, NEW MEXICO 87501	Revised 10-1-78	
FILE]		
U.S.G.S.		Sa. Indicate Type of Lense	
LAND OFFICE		Store X From	
DPERATOR		5, State Oil & Gas Lease No.	
		A-1543-1	
CHAID	NA MOTICES AND DEPORTS OF THE	11.11.11.11.11.11.11.11.11.11.11.11.11.	
DUNUK TORM FOR PRO	RY NOTICES AND REPORTS ON WELLS		
USE "APPLICAT	ION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
. OH		7, Unit Agreement Name	
WELL GAS X	OTHER-	ţ	
2. Name of Operator		8. Farm or Lease Lame	
Gulf Oil Corporat	tion		
. Address of Cretator		Graham State (NCT-F)	
,	-1.1 - and 00040	9. Weil No.	
P. O. Box 670, Ho	odds, NM 88240	j 5	
t. Location of *e.:		10. Field and Poor, or Widcat	
UNIT LETTER P	660 FEET FROM THE South LINE AND 660 FEE	Monument McKee	
	FEE.	TROM HOHOMERE MCKEE	
East	36		
THE LINE, SECTIO	ON 36 TOWNSHIP 198 RANGE 36E	WARM.	
mmmmmmm		<u> - ΔΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙΙ</u>	
	12. Flyvation (Show whether DF, RT, GR, etc.)	12. County	
	3586' GL	Too Allillilli	
Charles		Lea (\\\\\\\	
Check /	Appropriate Box To Indicate Nature of Notice, Report of	or Other Data	
NOTICE OF IN		UENT REPORT OF:	
PERFORM REMEDIAL WORK	21 MG AND ABANDON REMEDIAL WORK	J	
TEMPORARILY ASANDON	COMMENCE DRILLING OPNS.	ALTERING CASING	
PULL OR ALTER CASING		PLUG AND ABANDONMENT	
	CHANGE PLANS CASING TEST AND CEMENT JOB		
OTHER P&A to 5050; TA	OTHER		
64HER 1001 CO 3030 ; IA	5050' to surface X		
7. Describe in great or Completed Co.			
work) SEE SULE 1103.	erations (Clearly state all pertinent details, and give pertinent dates, inc	luding estimated date of starting any proposed	
POH with tubing & page	cker. Set CIBP at 9475'; circulate abandonme	ont and a cost	
on top of CIBP; spot	100' cement 6890'-6790'; spot 100' cement 51	sic mud. Spot 35' cement	
4500'; cap with 35'	cement. WOC. GIH with tubing open-ended; ta	150'-5050'. Set CIBP at	
late hole Test cas	ing to 500% with tubing open-ended; to	ag top of cement. Circu-	
more. Test cas.	ing to 500#. ND BOP, NU tree; inspect tubing	g & packer.	
		-	
	•		
3. I hereby cer iv that the information at	bove is true and complete to the best of my knowledge and belief.		
	A second to the out of my knowledge and belief.		
(1) (1) (1) A	_		
CNEO UCSUNL	Area Engineer	9-24-80	
		J-24-0U	
Orig. Signe	d by		
John Runy	van	SEP 25 1980	
	TITLE	3F P / 1 PAIL	