

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NEW MEXICO OIL CONSERVATION COMMISSION

Aug 26 1 20 PM '65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
E-3290

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Stelly Oil Company	8. Farm or Lease Name Mexico U
3. Address of Operator Box 730 - Hobbs, New Mexico	9. Well No. 2
4. Location of Well UNIT LETTER G 1650 FEET FROM THE North LINE AND 1650 FEET FROM THE East LINE, SECTION 8 TOWNSHIP 19-S RANGE 38-E NMPM.	10. Field and Pool, or Wildcat Hobbs
15. Elevation (Show whether DF, RT, GR, etc.) 3610' IF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in and rig up pulling unit.
2. Pull rods and tubing.
3. Clean well out with sand pump.
4. Perforate 5-1/2" OD casing from 4079-4100' with a total of 6 holes.
5. Set retrievable bridge plug at 4005'.
6. Treat through 5-1/2" OD casing perfs. 4079-4100' with 1000 gals. acid.
7. Scrub and test.
8. Pull retrievable bridge plug at 4005'.
9. Treat through perfs. 4079-4100' and open hole section 4111-4164' with 20000 gals. lease oil & 20000 # 20/40 sand,
10. Run tubing and rods.
11. Pump and test well.
12. Rig down and move out pulling unit.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(ORIGINAL SIGNED) **H. E. Asb**

SIGNED _____ TITLE **District Superintendent** DATE **August 25, 1965**

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: