

STATE OF NEW MEXICO  
OIL AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form O-103  
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-4086	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. Unit Agreement Name

8. Farm or Lease Name

STATE C

9. Well No.

2

10. Field and Pool, or Widest

EUNICE MONUMENT (G-SA)

UNIT LETTER H 1980 FEET FROM THE NORTH LINE AND 660 FEET FROM  
THE EAST LINE, SECTION 24 TOWNSHIP 19-S RANGE 36-E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

3708' DF

12. County

LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	REQUEST FOR EXTENSION OF TEMPORARY ABANDONMENT <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WELL TEMPORARILY ABANDONED BY PULLING PRODUCTION EQUIPMENT AS REPORTED ON FORM C-103 APPROVED JUNE 22, 1955. WE WISH TO EXTEND THIS WELL'S TA'D STATUS FOR ONE YEAR AS THIS WELLBORE IS BEING EVALUATED IN A GRAYBURG WATERFLOOD STUDY AND FOR UPHOLE POTENTIAL. WE PROPOSE TO PROPERLY TEMPORARILY ABANDON AS FOLLOWS:

1. Run gauge ring and junk basket to 3775'. <sup>35</sup>
2. Set a CIBP @ 3750' and cap w/2 sx cmt (20' minimum).
3. Circulate inhibited water, test casing to 300 psi, and temporarily abandon.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. Fore A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE MARCH 1, 1985

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR

TITLE

DATE

MAR - 5 1985