

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-22572
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-284

<p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>7. Lease Name or Unit Agreement Name  Hot Tamale State</p>	
<p>1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry</p>		<p>8. Well No. 1</p>	
<p>2. Name of Operator Nearburg Producing Company</p>		<p>9. Pool name or Wildcat West Osudo Morrow</p>	
<p>3. Address of Operator P. O. Box 31405, Dallas, TX 75231-0405</p>			
<p>4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>north</u> Line and <u>660</u> Feet From The <u>east</u> Line Section <u>34</u> Township <u>20S</u> Range <u>35E</u> NMPM Lea County</p>			
		<p>10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3680.0' GR</p>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

01/16/90 POOH w/432 jts 2-7/8" N-80 tbg (13,440'), SN, and Baker Lok-Set pkr (2-3/8"). Set bridge plug @ 13,400'. Made 2 dump bailer runs, dump 35' cement on top of plug.

01/18/90 Start in hole w/2-7/8" tbg open ended to spot bottom plugs.

01/19/90 Finish TIH to 11,050'. Mix mud and loaded hole w/mud. Spotted 25 sx plug from 11,050'-10,950' and spotted plug from 8950'-8850'.

01/22/90 Cut 5-1/2" casing @ 6195'. LD 5-1/2" casing.

01/23/90 Finish pulling casing. Recovered total of 6195' of casing. RU and run tbg to 6245'. Spot 50 sx plug (stub plug) @ 6245'.

01/24/90 Tag plug @ 6253' (witnessed by NMOCD). POOH to 5550', spot 50 sx plug @ base of surface. Pull up 20 stands and waited 4 hours. Ran back and tagged plug. PU to 2000' and spot 20 sx plug from 2000'-1900'. Finish LD tbg, set 10 sx surface plug.

01/25/90 Cut off 9-5/8" casinghead and set dryhole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Machelle Byrum TITLE Production Secretary DATE 1/29/90

TYPE OR PRINT NAME Machelle Byrum TELEPHONE NO. 214/739-1778

(This space for State Use)

APPROVED BY P.A. Padler TITLE OIL & GAS INSPECTOR DATE NOV 28 1990

CONDITIONS OF APPROVAL, IF ANY: