

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLE
(Other instructions
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
N.M. 0378446-A

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry Hole		7. UNIT ACQUISITION NAME
2. NAME OF OPERATOR Kirball Production Company		8. FARM OR LESSEE NAME Federal 34
3. ADDRESS OF OPERATOR 2820 First City Natl. Bank Bldg., Houston, TX 77002		9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* Use this space if below surface) 660' FSL & FEL of Sec. 34		10. FIELD AND POOL, OR WILDCAT Wildcat
14. HIDEOUT NO.	15. ELEVATIONS (Show whether DF, ET, CR, etc.)	11. SEC., T., R., N., OR BEK. AND SURVEY OR AREA Sec 34 T20S R33E
		12. COUNTY OR PARISH 13. STATE Lea N. Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and points pertinent to this work.) *

Well temporarily abandoned 5-6-73 w/150 sx cement plug from 3415' to 3020'. Swage and plug valve in casinghead @ surface. Propose to set 150 sx plug @ 1800-1400' with tubing and pump truck, plus 50 sx plug @ 550'-450', plus 10 sx plug in top of surface casing. Cut casing off below ground level and restore surface location.

18. I hereby certify that the foregoing is true and correct

SIGNED *E. H. Gulluback* TITLE Manager of Operations DATE 2/27/76

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
MAR 1 1976
ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side