

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-26179

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
B-10233

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
State KN-12

1. Type of Well:
OIL WELL GAS WELL OTHER Injection

8. Well No.
6

2. Name of Operator
Conoco, Inc.

9. Pool name or Wildcat
Eumont Yates 7 Rvrs Queen

3. Address of Operator
10 Desta Dr. Ste 100W, Midland, TX 79705

4. Well Location
Unit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line
Section 12 Township 19S Range 36E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3738'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: _____ <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: _____ <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to temporary abandon this well by the following procedure:

1. POOH with rods, pump, and production tubing.
2. Clean out wellbore to 3800'.
3. Set CIBP at 3775' and circulate packer fluid to surface.
4. Notify the Hobbs NMOCDD office 24 hrs. prior to testing.
5. Pressure test casing to 500 psi for 30 minutes.

This well will be studied for shallow gas recompletion potential.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry W. Hoover TITLE Sr. Conservation Coordinator DATE 6/9/94
TYPE OR PRINT NAME Jerry W. Hoover TELEPHONE NO. (915) 686-6548

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL IN THE POSSESSION OF THE
OIL CONSERVATION DIVISION
JUN 13 1994

SW B

RECEIVED

1991

SPRINGFIELD
OFFICE