

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-025-26314

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
Xeric Oil & Gas Corporation

3. Address of Operator  
P.O. Box 352, Midland, Texas 79702

4. Well Location  
Unit Letter A : 660 Feet From The North Line and 560 Feet From The East Line  
Section 30 Township 20-S Range 36-E NMPM Lea County

7. Lease Name or Unit Agreement Name

Union State

8. Well No.  
2

9. Pool name or Wildcat  
Osudo, North (Morrow)

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Mix & spot sand in methanol/KCL slurry to cover perfs and fill casing to 11,280' tag sand w/slickline. Load tbg w/KCL. Sting out of Baker Model N Pkr & POOH w/tbg & seal assembly. RIH w/profile nipple, 15' sub, profile nipple, 15' sub, latch type seal assembly, on/off tool w/profile nipple & 3 1/2" workstring. Lat into packer. RIH w/coil tbg & circ. w/foam to uncover Morrow Perfs 11,338'-11,3 Frac Morrow Perfs. Flow back. RIH w/coil tbg to jet back load & sand as necessary. Set blanking plug in lower profile nipple. Rel. on/off tool. POOH w/3 1/2" workstring. RIH w/production string. Retrieve plug. Return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE R.C. Barnett TITLE Vice Pres. - Land

DATE 6/12/96

TYPE OR PRINT NAME R.C. Barnett (915) 683-3171

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED APPROVAL  
DISTRICT III

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_

DATE JUN 19 1996

CONDITIONS OF APPROVAL, IF ANY:

10/10/10

