NO. OF COPIES RECEIVED							
DISTRIBUTION	NEW	NEW MEXICO OIL CONSERVATION COMMISSION				Form C-101	
SANTA FE					Revised 1-1-	65	
FILE						e Type of Lease	
U.S.G.S.					STATE	X FEE	
LAND OFFICE					.5. State Oil	& Gas Lease No.	
OPERATOR					A-	1375	
ADDLICATIO	U FOR REPUIT TO	DDUL DEEDEN A		·			
APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK  18. Type of Work					7777777		
Tal Type of Work					7. Unit Agre	eement Name	
b. Type of Well DRILL		DEEPEN	PLUG B	ACK X			
OIL GAS WELL WELL			SINGLE TT MILLS	TELE C	8. Farm or I		
2. Name of Operator	O.HER		ZONE X MULT	ZONE	State	E-8913	
Inle I Homen					9. Well No.		
Jake L. Hamon  3. Address of Operator					2 10. Field and Pool, or Wildcat		
611 Petroleum F	Building, Midlar	nd, Texas 79701	1			•	
		2100 South			Trides	ignated	
UNIT LETT	.R LOC	FE ZIOO FE	EET FROM THE	LINE			
AND 1830 FEET FROM	THE West LIN	E OF SEC. 20 TV	NP. 20S RGE. 361	NMPM			
			millim	Tim	12. County		
					Lea		
				<i>HHH</i>	HHH.	HHHHH	
			9. Proposed Depth 19	A. Formation	,	20, Rotary or C.T.	
			7700	Bone Sp	rino	Pulling Unit	
21. Elevations (Show whether DF)	<i>RT</i> , etc.) 21A. Kind	& Status Plug. Bond 21	lB. Drilling Contractor		22. Approx	. Date Work will start	
3637 GR 3661 KB	Blanke	et in Force			8-26	5-83	
23.	F	ROPOSED CASING AND	CEMENT PROGRAM				
SIZE OF HOLE				1	··	· · · · · · · · · · · · · · · · · · ·	
SIZE OF HOLE		WEIGHT PER FOOT		SACKS OF	CEMENT	EST. TOP	
17-1/2	12-3/4	35	381	400		Surface	
11"	8-5/8	24# & 28#	5618	2450		Surface	
7-7/8"	5-1/2	17 er 8.81	10,990	650		8,370'	
4-3/4"	3-1/2" line	er 8.81	11,473	<b>` 7</b> 5		10,650	
NOIL. THE above cas	sing was set whe	en well original	lly drilled.				
Propose:	sing was set whe	en well original	rry driffed.				
Propose:  1. Set squeeze reta	sing was set whe siner in $5-1/2$ "	en well original	rry driffed.	Baker Mo	del D pe	ermanent	
Propose:  1. Set squeeze reta  packer at 10,542	ainer in 5-1/2"	casing at 10,53	30' just above l		_		
Propose:  1. Set squeeze reta packer at 10,542  2. Squeeze with 65	ainer in 5-1/2" 2'. sks of cement,	casing at 10,53	30' just above l	etainer	to fil	L hole from	
Propose:  1. Set squeeze retapacker at 10,542  2. Squeeze with 65 squeeze retainer	sing was set when ainer in 5-1/2" 2'. sks of cement, to bottom of p	casing at 10,53 pumping 50 sks perforations at	30' just above l below squeeze 1 11,346'. Leave	etainer	to fil	L hole from	
Propose:  1. Set squeeze retapacker at 10,542  2. Squeeze with 65 squeeze retainer retainer to fill	ainer in 5-1/2" 2'. sks of cement, to bottom of p	casing at 10,53  pumping 50 sks perforations at ' casing above 1	30' just above l below squeeze 1 11,346'. Leave retainer.	etainer 15 sks	to fill	L hole from ent on top of	
Propose:  1. Set squeeze retapacker at 10,542  2. Squeeze with 65 squeeze retainer retainer to fill  3. Pull tubing up to	ainer in 5-1/2" 2'. sks of cement, to bottom of p 100' in 5-1/2' to 10,300' and s	casing at 10,53  pumping 50 sks perforations at 'casing above 1 spot 25 sk plug	30' just above l below squeeze 1 11,346'. Leave retainer.	etainer 15 sks	to fill	L hole from ent on top of	
Propose:  1. Set squeeze retapacker at 10,542  2. Squeeze with 65 squeeze retainer retainer to fill  3. Pull tubing up toplug at top of V	ainer in 5-1/2" 2'. sks of cement, to bottom of p 1 100' in 5-1/2' to 10,300' and s Volfcamp at 10,2	casing at 10,53 pumping 50 sks perforations at casing above 1 spot 25 sk plug	below squeeze in 11,346'. Leave tetainer.	retainer e 15 sks ack to 1	to fill of ceme	L hole from ent on top of to put 200'	
Propose:  1. Set squeeze retapacker at 10,542  2. Squeeze with 65 squeeze retainer retainer to fill  3. Pull tubing up toplug at top of W  4. Perforate squeeze	ainer in 5-1/2" 2'. sks of cement, to bottom of p 1 100' in 5-1/2' to 10,300' and s Nolfcamp at 10,2 te holes at 7850	casing at 10,53 pumping 50 sks perforations at casing above 1 spot 25 sk plug	below squeeze in 11,346'. Leave tetainer.	retainer e 15 sks ack to 1	to fill of ceme	L hole from ent on top of to put 200'	
Propose:  1. Set squeeze retapacker at 10,542  2. Squeeze with 65 squeeze retainer retainer to fill  3. Pull tubing up toplug at top of Warden	sing was set when diner in 5-1/2" 2'.  sks of cement, to bottom of p 1 100' in 5-1/2' to 10,300' and s Wolfcamp at 10,2 te holes at 7856 1/2" casing.	casing at 10,53 pumping 50 sks perforations at casing above 1 spot 25 sk plug 225'. O'. Set squeeze	below squeeze to 11,346'. Leave retainer. from 10,300' base retainer at 75	retainer e 15 sks ack to 1	to fill of ceme	L hole from ent on top of to put 200'	
Propose:  1. Set squeeze retapacker at 10,542  2. Squeeze with 65 squeeze retainer retainer to fill  3. Pull tubing up toplug at top of Warden at top of Warden and top squeeze cement behind 5-  5. Perforate and tests	sing was set when ainer in 5-1/2".  sks of cement, to bottom of plants in 5-1/2" to 10,300' and sholfcamp at 10,2 to holes at 7850-1/2" casing.  est Bone Springs	casing at 10,53  pumping 50 sks perforations at casing above a spot 25 sk plug 225'.  Set squeeze s from 7600' to	below squeeze to 11,346'. Leave retainer. from 10,300' base retainer at 75	retainer e 15 sks ack to 1	to fill of ceme	L hole from ent on top of to put 200'	
Propose:  1. Set squeeze retapacker at 10,542  2. Squeeze with 65 squeeze retainer retainer to fill  3. Pull tubing up toplug at top of Warden	sing was set when ainer in 5-1/2".  sks of cement, to bottom of plants in 5-1/2" to 10,300' and sholfcamp at 10,2 to holes at 7850-1/2" casing.  est Bone Springs	casing at 10,53  pumping 50 sks perforations at casing above a spot 25 sk plug 225'.  Set squeeze s from 7600' to	below squeeze to 11,346'. Leave retainer. from 10,300' base retainer at 75	retainer e 15 sks ack to 1	to fill of ceme	L hole from ent on top of to put 200'	
Propose:  1. Set squeeze retarpacker at 10,542  2. Squeeze with 65 squeeze retainer retainer to fill  3. Pull tubing up to plug at top of Warden at top of Warden and top squeeze cement behind 5-  5. Perforate and top squeeze cement behind 5-  6. Workover to begin	sing was set who ainer in 5-1/2" 2'. sks of cement, to bottom of p 100' in 5-1/2' to 10,300' and s Nolfcamp at 10,2 te holes at 7850-1/2" casing. est Bone Springs in approximately	casing at 10,53 pumping 50 sks perforations at casing above a spot 25 sk plug 225'. D'. Set squeeze s from 7600' to y 8-26-83.	below squeeze in 11,346'. Leave retainer. from 10,300' bare retainer at 75 7660'.	retainer = 15 sks ack to 1 750'. S	to fill of ceme 0,100' i	L hole from ent on top of to put 200'	
Propose:  1. Set squeeze retapacker at 10,542  2. Squeeze with 65 squeeze retainer retainer to fill  3. Pull tubing up toplug at top of Warden at top of Warden and top squeeze cement behind 5-  5. Perforate and tests	ainer in 5-1/2" 2'. sks of cement, to bottom of p 100' in 5-1/2' to 10,300' and s Volfcamp at 10,2 te holes at 7850 1/2" casing. est Bone Springs in approximately	casing at 10,53 pumping 50 sks perforations at casing above a spot 25 sk plug 225'. D'. Set squeeze s from 7600' to y 8-26-83.	below squeeze in 11,346'. Leave retainer. from 10,300' bare retainer at 75 7660'.	retainer = 15 sks ack to 1 750'. S	to fill of ceme 0,100' i	L hole from ent on top of to put 200'	

Title Petroleum Engineer

(This space for State Use)

AUG 2 2 1983 HOBBS OFFICE

. . .