

UNITED STATES DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO 88240 LEASE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well  gas well  other

2. NAME OF OPERATOR  
Great Western Drilling Company

3. ADDRESS OF OPERATOR  
P.O. Box 1659, Midland, TX 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 760' FNL, 1,780' FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
LC 055715

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Bordages

9. WELL NO.  
4

10. FIELD OR WILDCAT NAME  
Eunice-Monument

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Unit Letter C  
Sec. 33, T-19-S, R-37-E

12. COUNTY OR PARISH  
Lea

13. STATE  
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3593.6' RKB

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <input type="checkbox"/>	<input type="checkbox"/>

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Workover to Shut Water Off  
 Well Data: T.D. 3,950, PBD 3,948, Elev. 3,593.6' RKB  
 8-5/8" OD, 24#/ft. csg set @ 408.67'  
 4 1/2" OD, 10.5#/ft. csg set @ 3,950.33'  
 4 1/2" Csg Perfs: 3,742'-3,883' (77 holes)

11/19-27/85: Rigged up pulling unit, fished rods & tubing, cleaned out from 3,900'-3,950', recovered frac balls, sand, scale & gyp. Ran Baker AD-1 Pkr on 2-3/8" OD, tbg & set Pkr @ 3,713' above all perforations. Pressure tested csg & tbg annulus to 750 psi for 15 min, held no casing leaks. POH w/tbg & pkr, ran dump bailer on wireline & plugged back from 3,915' to 3,859' w/Cal seal, ran tbg & pump installations & placed well back on production.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct.

SIGNED M. H. Meyer TITLE Ass't. to Gen. Supt. DATE 12-19-85

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
 CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD  
SWD

JAN 3 1986

\*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

RECEIVED  
JAN 6 - 1971  
C. F. B. SERVICE  
HOUSTON, TEXAS