

C. L. CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER: PXA

2. Name of Operator
Amoco Production Company

3. Address of Operator
P. O. Box 68, Hobbs, New Mexico 8824C

4. Location of Well
UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM
THE West LINE, SECTION 6 TOWNSHIP 19-S RANGE 38-E N.M.P.M.

7. Unit Agreement Name
State H

8. Farm or Lease Name
State H

9. Well No.
4

10. Field and Pool, or Wildcat
Yates Wildcat

11. Elevation (Show whether DF, RT, GR, etc.)
3650' GL

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in service unit and killed well with 50 bbl fresh water. Pulled tubing and ran 5-1/2" CIBP. CIBP set at 2750'. Capped with 5 sx class C neat cement. Circulated hole with 55 bbl 10# brine water with 25# brine gel per sx. POH to 470' and pump 65 sx class C neat cement surface plug 470' to surface. Cut off wellhead and weld on cap. Erect permanent PXA marker and moved out service unit 5-31-83.

O+4-NMOCD,H 1-HOU R. E. Ogden RM 21.150 1-F. J.Nash, HOU Rm.4.206 1-CMH

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNED Charles M. Herring TITLE Administrative Analyst DATE 6-20-83

APPROVED BY A. D. [Signature] TITLE OIL & GAS INSPECTOR DATE JUN 29 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 21 1983

O.C.D.
HOBBS OFFICE