

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Alpha Twenty-One Production Company

Address of Operator

P.O. Box 1206, Jal, NM 88252

Location of Well

UNIT LETTER I 2310 FEET FROM THE South LINE AND 480 FEET FROM
THE East LINE, SECTION 22 TOWNSHIP 19-S RANGE 38-E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

Toni

9. Well No.

2

10. Field and Pool, or Wildcat
Nadine Drinkard-Abo

15. Elevation (Show whether DF, RT, GR, etc.)

3599' Ground Level

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PLUG OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER Completion Attempt ☒
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 3-19-82 Perforate Lower Drinkard section as follows: 7034', 7036', 7040', 7042', 7052', 7053', 7054', 7055', 7056'. 9 Perfs.
- 3-20-82 Acidize with 2000 gals. MOD-202 acid.
- 3-24-82 Acidize with 6000 gals. NE-FE acid (15%). Recovered fluid with slight show of oil.
- 5-31-82 Set CIBP at 7000'; dump 35' cement on top. Perforate the Upper Drinkard section as follows: 6622', 6624', 6626', 6628', 6630', 6632', 6650', 6652', 6658', 6670', 6674', 6678', 6706', 6712', 6716', 6718', 6720', 6727', 6739', 6796', 6798', 6800', 6802', 6804', 6812', 6844', 6859', 6861', 6868', 6884', 6889', 6893', 6898', 6903', 6914'. 35 Perfs
- 6-1-82 Acidize with 5000 gals 15% NE-FE acid. Prepare to frac well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

by Robert W. Lansford
Robert W. Lansford

TITLE V. Pres./Energy Resources

DATE 6-3-82

ORIGINAL SIGNED BY

APPROVED BY JERRY SEXTON

TITLE _____

DATE JUN 8 1982

CONDITIONS OF APPROVAL _____

RECEIVED
JUN 7 1982
C.F.B.
JUN 10 1982