

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-70

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- <u>Dry</u>	7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY	8. Farm or Lease Name <u>Best "B"</u>
3. Address of Operator P. O. BOX 68 HOBBS, NEW MEXICO 88240	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1780</u> FEET FROM THE <u>East</u> LINE, SECTION <u>23</u> TOWNSHIP <u>20-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Und. Queen</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3675.5' GR</u>	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to PxA the subject well as follows:
MISU and 10H w/ tubing. LITH with CTBP and set at 4800'. Cap with 35' Class C Neat cement.
Spot above CTBP 18 bbls of 10* Brine w/ 25* gel/Bbl. Pull up and spot a 25 sx Class C Neat
plug from 4365-4235' (13 3/4" csg shoe set at 4300'). Spot 94 bbls brine gel. Pull up and spot a
25 sx Class C Neat Cement plug from 2115-1985'. Spot 59 bbls of brine gel. Pull up and
spot a 25 sx Class C Neat plug from 665'-535' (16" csg shoe set at 597'). Spot above plug
18 bbls brine gel. Pull up and spot a 25 sx Class C Neat cement plug from 135' to
surface. Cap well and erect PxA Marker. MOSU.

0+5 NMOCD-H1-JRB 1-FJN 1-CMH 1-Mobil

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles M. Herring TITLE ADMINISTRATIVE ANALYST (SG) DATE 1-17-86

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR TITLE _____ DATE JAN 20 1986

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 17 1986

O.C.B.
HOBBS OFFICE