SUMPRIME	OTIOE : D.	
SUNDRY NO	OTICES AND REPORTS ON WELLS LS TO DRILL OR TO DEEPEN OR PLUS BACK TO A DIFFERENT PESSAYOTR. OR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS V		7. Unit Agreement Name
2. Name of Operator	THER-	8. Farm or Lease Name
TXO Production Corp. 3. Address of Operator		Jordan "B"
900 Wilco Bldg., Midland	d, TX 79701	9. Well No.
4. Location of Well		10. Field and Pool, or Wildow
UNIT LETTER O 660	FEET FROM THE South LINE AND 1980	West Osudo Morrow Gas
THE East LINE, SECTION_	11 TOWNSHIP 20-S RANGE 35-E	_ MAPM.
	15. Elevation (Show whether DF, RT, GR, etc.)	County
Check Appr	opriate Box To Indicate Nature of Notice, Report	Lea
NOTICE OF INTER		or Other Data DUENT REPORT OF:
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
OTHER	OTHER	
17. Describe Proposed or Completed Operatio	ons (Clearly state all pertinent details, and give pertinent dates, in	cluding estimated date of starting any proposes
Spud 20" hole 1:30 PM, 11- 2% Cacl. Circ 100 sx to pi	-19-84. Rn 16" 65# H-40 ST&C. Set @400'. it. PD @ 7:30 AM, 11-20. Test to 700# OF	Cmt. w/500 sx "c".
& shoe. Now drlg 14 3/4' ST&R + 4' float. Set @ 431 Tail w/500 sx "c" 2% Cacl.	"hole, thru 12-4-84. Rn 10 3/4" 45.5 # 16'. Cmt w/2250 sx 35/65 poz 10# gil, 8%. Circ 200 sx to pit. PD @ 9:45 PM, 12-t & collar & shoe. Drlg 9½" hole 12-5-84	% Drlg cmt, collar & 40.5 H S-80 & K-55 & salt, 1/4# flakes.
& shoe. Now drlg 14 3/4' ST&R + 4' float. Set @ 431 Tail w/500 sx "c" 2% Cacl.	" hole, thru 12-4-84. Rn 10 3/4" 45.5 # 16'. Cmt w/2250 sx 35/65 poz 10# gil, 89 . Circ 200 sx to pit. PD @ 9:45 PM, 12-	% Drlg cmt, collar & 40.5 H S-80 & K-55 & salt, 1/4# flakes.
& shoe. Now drlg 14 3/4' ST&R + 4' float. Set @ 431 Tail w/500 sx "c" 2% Cacl.	" hole, thru 12-4-84. Rn 10 3/4" 45.5 # 16'. Cmt w/2250 sx 35/65 poz 10# gil, 89 . Circ 200 sx to pit. PD @ 9:45 PM, 12-	% Drlg cmt, collar & 40.5 H S-80 & K-55 & salt, 1/4# flakes.
& shoe. Now drlg 14 3/4' ST&R + 4' float. Set @ 431 Tail w/500 sx "c" 2% Cacl. 1500# OK. Drlg cmt, float	" hole, thru 12-4-84. Rn 10 3/4" 45.5 # 16'. Cmt w/2250 sx 35/65 poz 10# gil, 8%. Circ 200 sx to pit. PD @ 9:45 PM, 12-t & collar & shoe. Drlg 9½" hole 12-5-84	% Drlg cmt, collar & 40.5 H S-80 & K-55 & salt, 1/4# flakes.
& shoe. Now drlg 14 3/4' ST&R + 4' float. Set @ 431 Tail w/500 sx "c" 2% Cacl. 1500# OK. Drlg cmt, float	" hole, thru 12-4-84. Rn 10 3/4" 45.5 # 16'. Cmt w/2250 sx 35/65 poz 10# gil, 89 . Circ 200 sx to pit. PD @ 9:45 PM, 12-	% Drlg cmt, collar & 40.5 H S-80 & K-55 & salt, 1/4# flakes.
& shoe. Now drlg 14 3/4' ST&R + 4' float. Set @ 431 Tail w/500 sx "c" 2% Cacl. 1500# OK. Drlg cmt, float	" hole, thru 12-4-84. Rn 10 3/4" 45.5 # 16'. Cmt w/2250 sx 35/65 poz 10# gil, 8%. Circ 200 sx to pit. PD @ 9:45 PM, 12-t & collar & shoe. Drlg 9½" hole 12-5-84	% Drlg cmt, collar & 40.5 H S-80 & K-55 & salt, 1/4# flakes.

CONDITIONS OF APPROVAL, IF ANY:

A STATE OF THE STA

DEC 26 1984

O. C. D.

NECEIVED

OEC 28 1984

O.C.D.
HOBBS OFFICE