

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different interval.
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

1. NAME OF OPERATOR

Siete Oil and Gas Corporation

2. ADDRESS OF OPERATOR

P. O. Box 2523 Roswell, New Mexico 88202

3. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FNL & 660' FWL Unit Letter E

4. PERMIT NO.

API # 30-025-70214

5. ELEVATIONS (Show whether M., FT., OR, etc.)

3495' GR

6. LAND DESIGNATION AND BUREAU NO.

NM 58820

7. IF APPLICABLE, ALLOTTEE OR TRACT NAME

8. NAME ON LEASE NAME

Kachina Federal

9. WELL NO.

1

10. FUEL AND FUEL, OR WILDCAT

Wildcat West Leuk. Delaware

11. SEC. T., R., N., OR S.W., AND QUAD NO. AREA

Sec. 6: T20S R32E

12. COUNTY OR PARISH

Lea

13. STATE

NM

14. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

WELL OR ALTER CASING

MULTIPLE COMPLETS

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT ON:

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and cover pertinent to this work.)*

- 12/29/87
1. Start pumping between 8 5/8" & 7" casing - loaded annulus w/2 bbls. fluid - Pressured up to 300 PSI - would not feed.
 2. Set CIBP @ 5800' and tested to 2000 PSI
 3. Set 100' plug @ 5828'
 4. Set 100' plug @ 4211'
 5. Set 100' plug @ 2529'
 6. Set 100' plug @ 847'
 7. Set 100' plug @ 100' to surface
 8. Install dry hole marker.

ACCEPTED FOR RECORD

JAN 5 1988

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED J.D. Jester

TITLE V.P. Drilling and Production

DATE 12/31/87

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side