

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-30539

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
OXY USA Inc.

3. Address of Operator
P. O. Box 50250, Midland, TX 79710

4. Well Location
Unit Letter P : 660 Feet From The South Line and 660 Feet From The East Line

Section 29 Township 19S Range 36E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3672' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. T.D. 10275'. Lime Shale & Dolomite. Plugged & Abandoned. Drilled 7-7/8" hole from 3490' to a T.D. of 10275'. Drill stem tests were ran from 8480' - 9446' (copies attached). We received verbal approval from Jerry Sexton w/NMOCD in Hobbs, NM to P&A the well in the following manner:

- 1) Set 50 sx. Cl.H cement plug @ 10008' - 9880'
- 2) Set 125 sx. Cl.H cement plug @ 8990' - 8740'
- 3) Set 100 sx. Cl.H cement plug @ 8627' - 8475'
- 4) Set 50 sx. Cl.H cement plug @ 8370' - 8270'
- 5) Set 50 sx. Cl.C cement plug @ 5569' - 5469'
- 6) Set 50 sx. Cl.C cement plug @ 4769' - 4669'
- 7) Set 75 sx. Cl.C cement plug @ 3615' - 3365' (1/2 In & 1/2 Out 8-5/8" csg.)
- 8) Set 35 sx. Cl.C cement plug @ 1742' - 1642'
- 9) Set 10 sx. Cl.C cement plug @ 100' - surface.

Set a 4" Dry Hole Marker 4' above ground to designate P&A location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE F. A. Vitrano TITLE Dist. Oper. Mgr. - Prod. DATE 4-10-89

TYPE OR PRINT NAME F. A. Vitrano (915) TELEPHONE NO. 685-5717

(This space for State Use)

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE JUN 14 1989

CONDITIONS OF APPROVAL, IF ANY: