Submit 3 Copies

## State of New Mexico

Form C-103

TELEPHONE NO. 214/739-1778

I 20%, Minerals and Natural Resources Departmen to Appropriate District Office Revised 1-1-89 OIL CONSERVATION DIVISION **DISTRICT I** WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-025-31007 DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE FEE XX DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: WELL X WELL East Pearl 31J 2. Name of Operator 8 Well No. Nearburg Producing Company 3. Address of Operator 9. Pool name or Wildcat P.O. Box 823085, Dallas, Texas 75382-3085 Osudo Morrow, North 4. Well Location . 1,650 Feet From The \_ South Line and 1,650 Unit Letter \_ Feet From The <u>East</u> Line 31 **19S** 36E Section Township Range Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,656.6' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB Activity OTHER: XX OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Spot 50 sx plug from 11,150' to 10,792'. Spot 25 sx plug from 01-28-91: 8,329'to 8,205'. Free point & cut 7" casing @ 7,156'. 01-29-91: Pull 7,156' (173 jts) of 7" casing. Spot stub plug 75 sx from 7,200' to 6,990'. WOC 4 hrs. Tagged plug 01-30-91: 01-31-91: @ 6,995'. Displaced hole w/gelled brine water (25# per bbl). 02-01-91: Ran CCL-Gamma Ray log. Set CIBP @ 5,350'. Dumped 35' cement on plug. Perforated San Andres from 5,240'-243' and 5,256'-64'. 2 JSPF (26 holes). Swabbed dry. Acidized w/200 gal 15% NEFE. 02-02-91: Swabbed dry. 02-03-91: Acidized w/1,000 gal 15% NEFE & 40 balls, swabbed dry. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Production Secretary DATE 2/13/91 SIGNATURE

APTROVED BY-

Machelle Byrům

TYPE OR PRINT NAME